



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI21007543/Etf3e2	
			Date: 19/10/2021	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SFN 8833R
	Policy No.	DH0M120053472000	Coverage (\$)	0.00
	Claim No.	M12D16122107	Excess (\$)	750.00
	Assign From	JOSEPHINE WONG	Assign Date	12/07/2021
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. X3	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	WBATR12070LC94405	Colour	WHITE
	Odometer	39555 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/50 R19	PIRELLI	5 mm
	L/H Front Tyre	245/50 R19	PIRELLI	5 mm
	R/H Rear Tyre	245/50 R19	PIRELLI	5 mm
	L/H Rear Tyre	245/50 R19	PIRELLI	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/07/2021	Inspection Date	13/07/2021
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks				
	A)THE MARKET VALUE IS S\$165,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	