

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0577/2021/JT
DATE : 13-Jul-21
WIP : 35183

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 15/7/2021
YOUR INSURED VEH NO :SHC 8588 U

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHAM SAY HONG
ADDRESS : BLK 209 BISHAN STREET 23
#04-365
SINGAPORE 570209
TELEPHONE : HP +65 8233 1488
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5106443926-02
VEHICLE NO : **SGC 8588 U**
MODEL CODE : A4 SEDAN 1.4 TFSI
MODEL YEAR : 30/12/2016
ENGINE NO : CVN 022756
CHASSIS NO : WAUZZZF46HA063165
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Jul-21
PLACE OF ACCIDENT : 8 ANG MO KIO AVE 2, THE PANAROMA
(B1 CARPARK)

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGC 8588 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	S/N \$ 360.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 5,002.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 900 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,111.00	
2	FRONT BUMPER FIXING PARTS	1	TBC	
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 210.00	
5	FRONT BUMPER AIR GUIDE - RH	1	\$ 63.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH	2	\$ 135.00	
7	FRONT BUMPER GUIDE SECTION - RH	1	\$ 38.00	
8	FRONT BUMPER TOP COVER - RH	1	\$ 127.00	
9	CAUTION STICKER	1	\$ 14.00	
10	A/C STICKER	1	\$ 8.00	
11	FRONT FENDER - RH	1	\$ 767.00	
12	FRONT FENDER ATTACHMENT PARTS	1	\$ 202.00	
13	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 72.00	
14	FRONT FENDER BRACKET - RH	1	\$ 35.00	
15	FRONT FENDER DEFORMATION BRACKET - RH	1	\$ 49.00	
16	FRONT FENDER RIVET	6	\$ 20.00	
17	FRONT FENDER BRACE - RH	1	\$ 118.00	
18	FRONT WHEEL HOUSING LINER - RH	1	\$ 241.00	
19	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	TBC	
20	FRONT WHEEL SPOILER - RH	1	\$ 73.00	
SUB-TOTAL SPARE PARTS		:	\$ 4,354.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 900 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER STONE CHIP GUARD - RH	1	\$ 51.00	
22	FRONT FENDER TOP COVER - RH	1	\$ 31.00	
23	FRONT FENDER SIDE TOP COVER - RH	1	\$ 23.00	
24	FRONT HEADLIGHT - RH	1	\$ 7,693.00	
25	FRONT HEADLIGHT LIFT CYLINDER - RH	1	\$ 210.00	
26	SUNDRIES		\$ 250.00	
TOTAL SPARE PARTS		:	\$ 12,612.00	
TOTAL LABOUR CHARGES		:	\$ 5,002.00	
GRAND TOTAL		:	\$ 17,614.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT