

ESTIMATE TO REPAIR

VEHICLE NO. : SLA 4654 P
MAKE : HONDA
MODEL : VEZEL 1.5 X A
YEAR : 2015
CHASSIS NO : RU11102542

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 12-Jul-21
DATE OF ACCIDENT : 12-Jul-21
THIRD PARTY REF : SJN 2602 H/ CHINA TAIPING

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1PC	FRONT BUMPER				\$ 459.80
1PC	FRONT BUMPER TOW COVER				\$ 17.10
1PC	FRONT BUMPER FOG LAMP				\$ 327.70
1PC	FRONT BUMPER FOG LAMP COVER				\$ 45.00
1PC	FRONT BUMPER LOWER SPOILER				\$ 196.50
1PC	FRONT BUMPER RETAINER				\$ 17.50
1PC	FRONT BUMPER REINFORCEMENT				\$ 321.00
10PCS	FRONT BUMPER CLIPS		\$ 3.50		\$ 35.00
1PC	FRONT GRILLE OUTER				\$ 203.40
1PC	FRONT GRILLE LOWER				\$ 77.50
1PC	O/S HEAD LAMPS				\$ 1,952.70
1PC	O/S HEAD LAMPS BRACKET				\$ 35.00
1PC	O/S FRONT FENDER				\$ 421.10
1PC	O/S FRONT FENDER ARCH GARNISH				\$ 153.00
1PC	O/S FRONT FENDER UNDER SHIELD				\$ 130.00
8PCS	O/S FRONT FENDER UNDER SHIELD CLIPS		\$ 3.50		\$ 28.00
1PC	WASHER TANK				\$ 75.00
1PC	BONNET				\$ 892.30
1PC	BONNET INSULATOR				\$ 122.30
					\$ 5,509.90
	LESS 20%				\$ 1,101.98
					\$ 4,407.92
	TO PUTTY & SPRAY PAINT				\$ 1,000.00
	TO ANTI RUST				\$ 150.00
	TO CHECK FRONT WIRING & FOCUS HEADLIGHT				\$ 30.00
	LABOUR CHARGES				\$ 650.00
TG/TL	TOTAL				\$ 6,237.92

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel 65-64520893 Fax 65-64589127 Email: edmund@LTM.sg Website: www.LTM.sg

Co Reg No 199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

consent of