

Veron Chen (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Friday, 23 July 2021 9:36 AM
To: Veron Chen (LKKAuto)
Subject: RE: SKE 3750S

Dear Veron,

AUDIT CHECK DONE FOR SKE3750S, FOUND WHEEL ALIGNMENT REPORT IS NEEDED FOR UNDERCARRIAGE PARTS REPLACED & SURVEYOR MARKING NEED TO REVIEW.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Veron Chen (LKKAuto)
Sent: Friday, 23 July, 2021 8:41 AM
To: Simon Ho (LKKAuto)
Subject: SKE 3750S

Dear Simon

File for audit check.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)