



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21007575/R1uf3e2	
			Date: 19/08/2021	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHB 5206K	Veh. Inspected	SGZ 462E
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/07/21/2024	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	13/07/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	B.M.W. X2 SDRIVE18I	c.c	1499
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WBAYH120405P18374	Colour	WHITE
	Odometer	44713 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/45 R19	YOKOHAMA	6 mm
	L/H Front Tyre	225/45 R19	YOKOHAMA	6 mm
	R/H Rear Tyre	225/45 R19	YOKOHAMA	6 mm
	L/H Rear Tyre	225/45 R19	YOKOHAMA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	10/07/2021	Inspection Date	02/08/2021
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	