

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06

AMK AUTOPOINT SINGAPORE 568047

Tel No. : 62571289 Fax No. : 64837432

E-Mail : bodyfix@singnet.com.sg

Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #04/05
IOB BUILDING SINGAPORE 049711

Attention : Motor Claim Department

Contact : 63476100 Fax No. : 62244174

Estimate : ES210714

Date : 14/07/2021

Vehicle Num. : SMU 4394 Y

Make/Model : TOYOTA COROLLA ALTIS-2016

Chassis/Eng# : MR053REH104557094/1ZRX591597

Accident Date : 10/07/2021

Claim No. :

Reference :

Policy No. :

Not Notified
1/12/21
Resurvey After Repair
4 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|-----|------|----------------------------|--|--|
| 1. | 1PC | LIST ITEMS : | | |
| 2. | 1PC | FRONT BUMPER | | |
| 3. | 1PC | FRONT BUMPER REINFORCEMENT | | |
| 4. | 1PC | FRONT SUPPORT PANEL | | |
| 5. | 1PC | HEAD LAMP (LH) | | |
| 6. | 1PC | HEAD LAMP (RH) | | |
| 7. | 1PC | FRONT GRILLE | | |
| 8. | 1PC | LOGO | | |
| 9. | 1PC | BONNET | | |
| 10. | 1PC | BONNET HINGE - RH | | |
| 11. | 1PC | BONNET HINGE - LH | | |
| 12. | 1PC | FRONT FENDER (RH) | | |
| 13. | 1PC | FOG LAMP (FRONT -LH) | | |
| 14. | 1PC | FOG LAMP (FRONT -RH) | | |
| 15. | 1PC | FOG LAMP COVER LH | | |
| 16. | 2PCS | FOG LAMP COVER RH | | |
| | | FRONT BUMPER SIDE RETAINER | | |

List TotalS\$:

6,996.85

- | | | | | |
|----|-----|----------------------|--|--|
| 1. | 1PC | SPECIAL NETT ITEMS : | | |
| | | FRONT NO.PLATE | | |

Special Nett Total S\$:

40.00

LABOUR :

TO CHECK & TEST LIGHTING FUNCTIONS

RUST-PROOFING ON THE ACCIDENT AFFECTED PORTIONS

201
80.00
201
100.00

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06
 AMK AUTOPOINT SINGAPORE 568047
 Tel No. : 62571289 Fax No. : 64837432
 E-Mail : bodyfix@singnet.com.sg
 Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL STREET #04/05
 108 BUILDING SINGAPORE 049711

Attention : Motor Claim Department
 Contact : 63476100 Fax No. : 62244174

Estimate : ES210714

Date : 14/07/2021
 Vehicle Num. : SMU 4394 Y
 Make/Model : TOYOTA COROLLA ALTIS-2016
 Chassis/Eng# : MR053REH104557094/1ZRX591597
 Accident Date : 10/07/2021
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR TO REPLACE ABOVE PARTS, PANEL BEAT , REPAIR & RE-ALIGN DAMAGE PARTS		500 850.00
		SPRAY PAINT FRONT BUMPER, FRONT FENDER RIGHT AND OTHER AFFECTED AREAS		600 900.00
		Labour Total S\$:		1,930.00

SingDollars : Eight Thousand Nine Hundred Sixty-Six & Cents Eighty-Five Only

E. & O.E.

Total S\$: 8,966.85

for BODYFIX