



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: TEO KITTY			Ref: CS/ASM21007644/AGvce2 Date: 28/10/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 7114Z	Veh. Inspected	SMT 7949H	
Policy No.	VFX/P2419140	Coverage (\$)	0.00	
Claim No.	S1M03DMU	Excess (\$)	0.00	
Assign From	TEO KITTY	Assign Date	14/07/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA STREAM	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	RN61012362	Colour	BLUE	
Odometer	246612 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	6 mm	
L/H Front Tyre	205/55 R16	PIRELLI	6 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	12/07/2021	Inspection Date	02/08/2021	
Survey held at	MCS GARAGE 10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE SINGAPORE 417868			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	