

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# GBJ3356C

TP111

Model:

ISUZU TFS87JSR

Accident Date : 13/7/2021

Xiao Tong

20/3/2019

Location PIE (TUAS) NEAR ALJUNIED FLYOVER

MPATFS 87JJTO12088 SP: GBK1761Z (III)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Distorted</i>	1,170.00	924.	
2	1 pc	Rear bumper top garnish rubber <i>Del d</i>	428.00		
3	2 pcs	Rear bumper bracket <i>Best</i>	345.60		
4	1 pc	Rear tail-gate <i>Distorted</i>	1,370.00	1058.	
5	1 pc	Rear tail-gate lock <i>new</i>	156.80	X	
6	1 pc	Rear tail-gate handle <i>Not new</i>	148.00	X	
7	1 pc	Rear tail-gate hinges <i>Best</i>	160.00		
8	1 pc	Rear tail-gate hinges pin <i>Best</i>	60.00		
9	1 pc	Rear n/s tail lamp <i>crushed</i>	435.60	365.	
10	1 pc	Rear tail-gate 70 kmph emblem		15.00	
11	1 pc	Rear tail-gate 6 pax emblem		15.00	
12	1 pc	Rear tail-gate ISUZU emblem		68.00	
13	1 pc	Rear tail-gate D-MAX emblem		68.90	
14	1 pc	Rear end panel <i>Distorted</i>	465.40		
15	1 pc	Rear reg. no. plate <i>Best</i>		25.00	
16	1 pc	Rear n/s fender <i>Regis</i>	1255.60	X	
17	1 pc	Rear n/s fender body sticker <i>new</i>		300.00	180
Sub-Total:			5,995.00	491.90	0.00
			15%	0%	10%
After Less %:			5095.75	491.90	0.00
Labour					
1		To dismantle, welding, knocking and replace rear damage parts	1,400.00	800.	
2		To spray painting.	1,000.00	700.	
3		To re-seal anti rust	60.00		
4		To check wiring.	50.00	30	
Sub-Total:			2,510.00		
Total:			8097.65		

3806

3235.10

S.N: 371.90

1590

total: 5197

CP/P) ✓

Chan San Choon
Director
DipEng, AAE, MIMI, MSAE (Aust)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer


Signature:

Date: *15/07/21*

bizSAFE 8778 1999

Mobil 1

24 hr accident call
GBJ3356C ESTIMATEPg1



PAYNOW