

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

GST REG. NO : M2

ESTIMATE

LKK Auto Consultants hence notify

the Repairer of the following:

- To respray before resurvey
- To respray damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page No. : 1 of 4

Estimate No. : b1 58839
Date Estimated : 01/07/2021
Prepared By : Joseph Yaguel

- ESTIMATE REPAIR FOR -
Tay Junction
733 Bukit Timah Road
#01-01 Second Avenue Junction
Singapore 269748

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMJ3031J	WBATR92050LE26558	28/02/2019	X3 xDrive30i	36143

DESCRIPTION

To replace rear bumper panel and attachments

To respray rear bumper

To check electrical wiring system and lighting at the rear section for proper function.

Sundries.

VALUE
850 1,275.00
986 1,038.00
168 177.00
80/? 150.00

Total Labour 1: 2,640.00

DESCRIPTION

REAR BUMPER CARRIER

RH SIDE GUIDE FOR BUMPER

REAR BUMPER BOTTOM REINFORCEMENT

REAR BUMPER PANEL PRIMED (M/PMA)

REAR BUMPER BOTTOM TRIM PANEL (M)

DECOUPING RING PDC TORQUE CONVERTER

QTY	PRIC	VALUE
1	765.35	765.35
1	58.55	58.55
1	79.25	79.25
1	1,563.20	1,563.20
1	372.20	372.20
4	5.15	20.60

Total Parts : 2,859.15

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 15/07/21 01:00 Excess S\$

Surveyor's Name Rasul Sign

Surveyor's Tel 91000000 Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend 3 days

Labour 1	:	2,640.00
Parts	:	2,859.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	384.94

Grand Total : 5,884.09



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



supplementary

Estimate No. : **b1 58839**
Date Estimated : **01/07/2021**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Tay Junction
733 Bukit Timah Road
#01-01 Second Avenue Junction

Singapore 269748

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMJ3031J	WBATR92050LE265	28/02/2019	X3 xDrive30i	46809

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# LH SIDE GUIDE FOR BUMPER cra	130.27	1.00	0.00	130.27
# EXPANDING RIVET BLACK nec	1.36	10.00	0.00	13.58

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	143.85