ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550 Company Reg. No.: 201113667N GST Reg. No.: 201113667N

No.: 06420

Vehicle Insured : GBD71A

Accident Date : 12-Jul-2021

Date: 12-Jul-2021

Our Ref : 021102 (III) / CHAN

PAGE: 1

LOW YAN WANG

BLK 407 PANDAN GARDENS

#05-48

Singapore 600407

Not Norhains Pering After Paint

ESTIMATED COST OF REPAIR FOR TOYOTA PICNIC SGR2158M

			M. 1 222 22
1	pc	Tail gate	1,306.90
	pc	Tail gate glass moulding	Daipy 247.50 50 81 123.755N
1	pc	Tail gate rubber	247.50 5000
1	pc	Tail gate inner trim cover	ns 423.30 —
	pc	Tail gate inner lock	A1/In 566.40 2
1	pc	Tail gate wiper motor	566.40
1	DC	Tail gate logo	ne 70.90 -
1	pc	Tail gate "TOYOTA" emblem	ne 41.40
1	pc	Tail gate "PICNIC" emblem	48.40
1	pc	mail wate outer garnish	man 99.70 -
2	pcs	Tail gate lamp	@ S\$256.30 % 512.60 X
2	pcs	Tail gate license plate lamp	@ S\$ 42.90 CM 85.80 2
1	pc	Rear end panel	Mr. 116.10
1	pc	End panel top garnish elscm	M Dir 206.20
2	pcs	Rear fender inner trim cover	@ S\$786.40 Bu 1,572.80 L+
1	DC	Rear bumper fascia	
2	pcs	Rear bumper side retainer	@ S\$ 48.20 dsnil 96.40 L+
	-		
			6,578.30
			Less 25%: 1,644.58

1 pc Rear bumper reverse sensor(3pc

1 pc Rear w/s glass sealant

1 pc Rear no.plate with box

To remove & refix rear windscreen glass and conduct water leak test.

4,933.72 300sm nollem 350.00 sn 60.00 sn 40 50.00 sness

150.00 /201

LKK Auto Consultants hence notify

the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBD71A

Page: 2

To remove roof lining, front and rear seats, trim board and carpet

120.00 100/

To remove air con condenser, pipes and drier, vacuum and to recharge gas

Nr 120.00 X

To apply undersealing

100.00 601

To putty and spray replaced parts

750.00 650/

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

700.00

Total:

S\$ 7,333.72 =========

Singapore Dollars Seven Thousand Three Hundred and Thirty Three and Cents Seventy Two Only

Enquire Vehicle Registration Details

Vehicle Registration Details

Vehicle No. SGR2158M	
Make/ Model TOYOTA/PICNIC AUTO W/O ROOF RACK	
Vehicle Scheme -	
Current Propellant Petrol	
Chassis No. JTEGH23B900023045	
Vehicle Type Passenger Station Wagon/Jeep/Land Rover	
Owner's Details	
Owner Name:	
LOW YAN WANG	
Owner ID Type:	
Singapore NRIC	
NRIC/Passport/Company Cert No.:	
S1632393D	
Registered Address: APT BLK 407 PANDAN GARDENS #05-48 SINGAPORE 60	0407
Mailing Address:	
•	
Divide Detay	

Max Unladen Weight:

Registration Details Previous Vehicle No.: Effective Date of Ownership: 01 Oct 2019 Original Registration Date: 02 Feb 2007 Registration Date: 02 Feb 2007 No. of Transfers: IU Label No.: 1120869235 **Vehicle Specifications** Engine No.: 1AZ5542627 Chassis No.: JTEGH23B900023045 Year of Manufacture: 2006 Primary Colour: Black Secondary Colour: Passenger Capacity: 6 Engine Capacity / Power Rating: 1998 cc/-Maximum Power Output: 110.0 kW (147 bhp)

Vehicle Attachment 3: Additional Registration Fee (ARF) and COE Information Open Market Value: \$24,702.00 Additional Registration Fee Rate: 110.00 % Actual ARF Paid: \$27,173.00 Vehicle Lifespan Expiry Date: No Lifespan OPC Cash Rebate Eligibility: No QP during COE Bidding Exercise: \$12,000.00 COE No.: 2007020103002308E COE Expiry Date: 31 Jan 2027 COE Category: B - Car (1601cc & above) COE Registration Category: B - Car (1601cc & above) Quota Premium (QP) / Prevailing Quota Premium \$12,000.00/-PQP Paid \$52,660.00

1540 kg

2185 kg

Maximum Laden Weight:

Vehicle Attachment 1:
No Attachment

Vehicle Attachment 2: