

OOHRAY RENTAL PTE. LTD.

8 Kaki Bukit Avenue 4, Premier@Kaki Bukit #06-31 Singapore 415875

Tel: (65) 6661 9687 Fax: (65) 6241 6697

Estimate Repair List

14 July 2021

HHTPClaims21-47

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWER
SINGAPORE 068811

Attn: Motor Claims Department

**ACCIDENT INVOLVING SMX 6603 R & SHC 948 E ON 10/07/2021 ALONG TOH GUAN ROAD
(SERVICE ROAD) AT ABOUT 2245 HOURS**

Insured : HUA HONG PTE LTD
Vehicle Registration No : SMX 6603 R
Vehicle Make : TOYOTA
Vehicle Model : VOXY HYBRID 1.8X CVT
Vehicle Chassis No : ZWR800452750
Policy No : 5109921641-02-000358
Date of Accident : 10/07/2021

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper	923.825	\$ 3,122.75 de
2	2	Rear Bumper Side Retainer (LH/RH)	\$ 362.10	\$ 724.20 PHOE/HB
3	10	Rear Bumper Clips	\$ 5.00	\$ 50.00 zone
4	1	Rear Bumper Reflector (RH)		\$ 129.30 xny
5	1	Rear Tailgate	1812.1712	\$ 4,221.40 bt
6	1	Rear Tailgate Lock		\$ 1,606.83 xny
7	1	Rear Tailgate Weather Strip		\$ 1,253.31 xny
8	1	Rear Tailgate Emblem	67.80	\$ 214.50 ne
9	1	Rear Windscreen Moulding		\$ 118.80 ne
10	1	Rear End Panel		\$ 2,295.00 Ry
11	1	Rear End Panel Top Garnish		\$ 542.10 xny
				\$ 14,278.19
				Less 20%
				\$ (2,855.64)
				\$ 11,422.55
12	1	Sealant	NETT	\$ 45.00 ne
21	1	Rear Reverse Sensor	245 NETT	\$ 200.00 ne
To cut & weld rear end panel. Change rear bumper rear tailgate. Knocking all area affected by accident				\$ 800.00 500
To perform wire checking				\$ 50.00 30
To transfer rear tailgate mechanism to new tailgate				\$ 80.00 60
To dismantle & transfer rear tailgate mechanism & fittings to new tailgate				\$ 80.00 xny
To dismantle & refit rear windscreen				\$ 120.00 ✓
				\$ 12,797.55

OOHRAY RENTAL PTE. LTD.


8 Kaki Bukit Avenue 4, Premier@Kaki Bukit #06-31 Singapore 415875

Tel: (65) 6661 9687 Fax: (65) 6241 6697

ACCIDENT INVOLVING SMX 6603 R & SHC 948 E ON 10/07/2021 ALONG TOH GUAN ROAD (SERVICE ROAD) AT ABOUT 2245 HOURS

Estimate Repair List for vehicle SMX 6603 R - Toyota Voxy

Balance B/F	\$ 12,797.55	500
To spray rear end panel, rear bumper, rear tailgate and all affected area	\$ 800.00	450
		260
	\$ 13,597.55	
7% GST	\$ 951.83	1210
Total	\$ 14,549.38	



Authorised by Claims Dept

22,77.60
245
1210
\$ 37,32.60
4 days #

Taufik 97495749
WP - 21/7/6 @ 1pm
P/P Resurvey before paint
• 4 days
taufik@lkkauto.com
taufik@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: