

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	13/07/2021
Vehicle Reg. No.:	SHC3336B	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Vehicle Reg. Date:	01/04/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2C06971	Chassis No:	JTDKB3FU403079881
Odometer:	269399 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		

Present Location: COMFORTDELGRO.ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS	Amount
Parts	2,120.30
Miscellaneous Items	11.00
Labour	2,260.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,391.30
+ GST 7.00% (S\$)	307.39
Nett Amount (S\$)	4,698.69

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 15 Jul 2021)**Parts:** 144 TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC3336B/15/07/2021 08:52**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	25.00	0.00	*458.60 FLX ^R
2	1		*REAR BUMPER UNDER COVER	25.00	0.00	*552.60 FL ^{DEF}
3	1		*REAR BUMPER UNDER COVER LH	25.00	0.00	*232.00 FL [?]
4	1		*REAR FENDER LH	25.00	0.00	*836.70 FL ^{DD}
5	1		*REAR BUMPER MAT	25.00	0.00	*50.00 FL ^{NEC}
6	1		*REAR BUMPER REVERSE SENSOR	25.00	0.00	*135.70 FL ^{XSVL}
7	1		*REAR BUMPER ADVERTISEMENT	0	0.00	*50.00 FS ^{NEC}
8	1		*REAR FENDER ADVERTISEMENT	0	0.00	*100.00 FS ^{NEC}
9	1		*REAR DOOR ADVERTISEMENT	0	0.00	*100.00 FS ^{CTN}
10	1		*REAR FEUL LID STICKER	0	0.00	*20.00 FS ^{NEC}
11	1		*REAR BUMPER RETAINER LH	25.00	0.00	*94.80 FL [?]
12	1		*REAR DOOR COMFORT APP	0	0.00	*80.00 FS ^{NEC}

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,710.40
- List Item Discount on L Items (\$\$)	590.10
Total Parts (\$\$)	2,120.30

ComfortDelGro Engineering Pte Ltd/SHC3336B/15/07/2021 08:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	1,050 1,100.00
2	SPRAY PAINTING	New	730 800.00
3	REMOVE/REFIX REAR UPHOLSTERY	New	NN x 120.00
4	CHECK WIRING AND LIGHTING	New	NN x 60.00
5	TUFF COATING	New	40 120.00
6	REMOVE/REFIX REVERSE SENSOR	New	30 60.00
Gross Labour Cost (S\$)			2,260.00

ComfortDelGro Engineering Pte Ltd/SHC3336B/15/07/2021 08:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NAZ LKX
15/7/2021 1635
PH
3 DAYS
CHECK ITEM PHOTOS
BY PAINT PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: