



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21007680/Rqf3e2	
			Date: 27/05/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHD 6126R	Veh. Inspected	SMD 4575G
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/07/21/2013	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	15/07/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HYUNDAI ELANTRA 1.6 GLS	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	KMHD841CMJU729385	Colour	BLUE
	Odometer	25035 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	NEXEN	6 mm
	L/H Front Tyre	195/65 R15	NEXEN	6 mm
	R/H Rear Tyre	195/65 R15	NEXEN	6 mm
	L/H Rear Tyre	195/65 R15	NEXEN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR, REAR O/S AND REAR N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	08/07/2021	Inspection Date	15/07/2021
	Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	