



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 1

Vehicle No. SLR4244A HONDA SHUTTLE

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR ADJUSTMENT	
	PARTS (LIST ITEMS)					
1	FRONT BUMPER			1050.50		
2	FRONT BUMPER SIDE RETAINER RH & LH @\$45.00			RH x 90.00		
2	FRONT BUMPER FOGLAMP COVER RH & LH @\$101.00			RH x 202.00		
1	FRONT BUMPER REINFORCEMENT			510.00		
1	FRONT BUMPER LOWER GRILLE			216.00		
1	FRONT HEADLAMP LH			2250.00		
2	FRONT HEADLAMP LOWER BRACKET LH			45.60		
1	FRONT FENDER RH			456.80		
1	FRONT FENDER INNER SHEILD RH			116.50		
1	FRONT WASHER TANK			318.00		
1	FRONT WASHER TANK MOTOR			352.00		
1	FRONT SUPPORT PANEL			510.00		
		less		6117.40		
			20%	1223.48	20%	
				4893.92		
	SPECIAL NETT ITEMS					
1 SET	FRONT BUMPER CLIPS			100.00		
1 SET	FRONT SUPPORT PANEL CLIPS			100.00		
1 SET	FRONT FENDER INNER SHEILD CLIPS			80.00		
		Total Parts		5173.92		

Supplementary Part

Front grille. con



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SLR4244A HONDA SHUTTLE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	OUR ASSESSMENT (\$)
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1400.00	200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	400
3	To remove and refix wiring at damaged areas	180.00	30
4	To perform anti rust treatment on affected areas	150.00	x
5	To check headlamp beam	120.00	30
6	To conduct water seepage test	100.00	x
	Labour Total :	3150.00	
TOTAL (PARTS & LABOUR):		8323.92	

Taufik 97895749
WP
16/7/21 @ 12pm
03 days
taufik @ hantcom -

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: