

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	🖨	📄	Find Next
---	---	----------	---	---	---	---	--------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref: CS/ICS21007704/Utf3		
10 EUNOS ROAD 8		Date: 16/07/2021		
SINGAPORE POST CENTRE #09-04A				
SINGAPORE 408600		Code: ICS		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLQ 5533P	Veh. Inspected	SLD 1254P	
Policy No.		Coverage (\$)	0.00	
Claim No.	DMPC2100230H/02/CT	Excess (\$)	0.00	
Assign From	CRYSTABELLE TAN GEK PENG	Assign Date	16/07/2021	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/07/2021	Inspection Date	16/07/2021	
Survey held at	15 Kaki Bukit Road 4 #01-05/53 Bartley Biz Centre			
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				