



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: CYNTHIA		Ref: CC4/ASM21007717/Gpa3q2 Date: 01/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8167P	Veh. Inspected	FBQ 1880G
Policy No.	P2419138	Coverage (\$)	0.00
Claim No.	S1M03DHP	Excess (\$)	0.00
Assign From		Assign Date	16/07/2021
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA JUPITER 115 Z1	c.c	114
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MH3UE1120KJ228606	Colour	BLUE
Odometer	54703 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	70/90-17	MICHELIN	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	MICHELIN	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S & N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/07/2021	Inspection Date	16/07/2021
Survey held at	KARZ WORKS PTE LTD 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	