

AERO GARAGE PTE LTD  
 BLK 160 SIN MNG DRIVE  
 #08-07  
 SINGAPORE 575722

*Not Authorized  
 11 Rmp @ 2950/h  
 Runny After Paint  
 4 days*

Make/ Model : TOYOTA VOXY Date: 28.08.2021  
 Chassis No : ZWR800448784 Vehicle No: SMW 5426Y  
 Date of Accident / Time: 13/07/2021 1400HRS Date of Reg: 26.11.2020

ESTIMATE

ITEMS	PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE
1	REAR BUMPER <i>1021.10</i>	1	<i>BT/CM</i>	\$ 1,060.20 ✓
2	REAR BUMPER TOW HOOK COVER	1		\$ <i>Sm</i> 65.15 X
3	REAR BUMPER REFLECTORS	2	\$ 68.30	\$ <i>Sm</i> 136.60 X
4	REAR BUMPER SIDE RETAINERS LONG	2	\$ 110.20	\$ <i>Sm</i> 220.40 X
5	REAR BUMPER SIDE RETAINERS SHORT	2	\$ 65.10	<i>sdj 0.7</i> 130.20 ✓
6	REAR BUMPER BRACKETS	1		\$ <i>R</i> 55.60 X
7	REAR BUMPER SENSOR WIRE HARDNESS	1		\$ <i>Sm</i> 415.10 X
8	REAR REVERSE SENSORS	1		\$ <i>CM</i> 509.15 <i>200JA</i>
9	REAR SIDE BUMPER	2	\$ 210.40	\$ <i>Sm</i> 420.80 X
10	TAILGATE	1		\$ <i>BT</i> 1,416.35 ✓
11	TAILGATE OUTER GARNISH (CHROME)	1		\$ <i>Sm</i> 680.19 X
12	TAILGATE INNER TRIM	1		\$ <i>Sm</i> 690.10 X
13	TAILGATE INNER TRIM COVER	1		\$ <i>Sm</i> 292.90 X
14	TAILGATE THIRD BRAKE LAMP	1		\$ <i>Sm</i> 210.15 X
15	TAILGATE NUMBER PLATE LAMPS	2	\$ 69.00	\$ <i>Sm</i> 138.00 X
16	TAILGATE LOGO	1		\$ <i>Sm</i> 74.10 ✓
17	TAILGATE HYBRID EMBLEM	1		\$ <i>Sm</i> 82.30 ✓
18	TAILGATE POCKET HANDLE	1		\$ <i>Sm</i> 50.20 X
19	TAILGATE STOPPER REAR	2	\$ 45.30	\$ <i>Sm</i> 90.60 X
20	TAILGATE STOPPER SIDE	2	\$ 48.15	\$ <i>Sm</i> 96.30 X
21	TAILGATE LATCH	1		\$ <i>R</i> 43.10 X
22	TAILGATE DAMPERS	2	\$ 299.45	\$ <i>Sm</i> 598.90 X
23	TAILGATE HINGES	2	\$ 65.10	\$ <i>R</i> 130.20 X
24	TAILGATE INNER LOCK	1		\$ <i>R</i> 509.40 X
25	TAILGATE DETECTOR	1		\$ <i>Sm</i> 410.35 X
26	TAILGATE SWITCH CONNECTOR	1		\$ <i>Sm</i> 201.10 X
27	TAILGATE TOP INNER TRIM	1		\$ <i>Sm</i> 292.10 X
28	TAILGATE SIDE INNER TRIM	2	\$ 210.11	\$ <i>Sm</i> 420.22 X
29	TAILGATE WEATHERSTRIP	1		\$ <i>Sm</i> 399.40 X
30	TAILGATE LOWER GARNISH RETAINERS	2	\$ 65.10	\$ <i>Sm</i> 130.20 X
31	TAILAMPS ASSY	2	\$ 818.40	\$ <i>Sm</i> 1,636.80 X
32	TAILAMPS PANELS	2	\$ 356.40	\$ <i>R</i> 712.80 X
33	TAILAMPS INNER PANEL	2	\$ 616.40	\$ <i>R</i> 1,232.80 X
34	REAR END PANEL	1		\$ <i>R</i> 755.40 X
				\$ 14,307.16

C/F \$ 14,307.16

AERO GARAGE PTE LTD  
 BLK 160 SIN MNG DRIVE  
 #08-07  
 SINGAPORE 575722

B/F \$ 14,307.16

35	REAR END PANEL TOP GARNISH	1		\$ <i>5h</i> 349.10	X
36	REAR END PANEL EXTENSION PANEL	1		\$ <i>R</i> 808.10	X
37	REAR FLOOR PANEL	1		\$ <i>R</i> 606.35	X
38	REAR FLOOR PANEL CARPET TRIM	1		\$ <i>h</i> 403.10	X
				\$ 16,473.81	
				Less 25%	\$ 4,118.45
				\$ 12,355.36	

ITEMS	PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE	
1	REAR BUMPER CLIPS	1		\$ <i>h</i> 50.00	SN ✓
2	REAR BUMPER SIDE BUMPERS CLIPS	2	\$ 50.00	\$ <i>h</i> 100.00	SN X
3	REAR NUMBER PLATE W/ HOLDER	1		\$ <i>h</i> 120.00	SN X
4	TAILGATE WINDSCREEN SEALANT	1		\$ <i>h</i> 100.00	SN <i>40h</i>
5	TAILGATE WINDSCREEN INNER SEAL	1		\$ <i>h</i> 80.00	SN <i>30h</i>
6	TAILGATE OUTER GARNISH CLIPS	1		\$ <i>h</i> 50.00	SN X
7	TAILGATE INNER SHIELD	1		\$ <i>h</i> 50.00	SN X
8	TAILGATE INNER TRIMS CLIPS	1		\$ <i>h</i> 50.00	SN X
10	REAR END PANEL TOP GARNISH CLIPS	1		\$ <i>h</i> 50.00	SN X
11	REAR END PANEL INSULATION SEAL	1		\$ <i>h</i> 120.00	SN X
12	REAR FENDER INNER TRIMS CLIPS	2	\$ 30.00	\$ <i>h</i> 60.00	SN X
13	REAR FENDER INNER TOP TRIMS CLIPS	1		\$ <i>h</i> 50.00	SN X
14	REAR FENDER INNER COWLING CLIPS	2	\$ 30.00	\$ <i>h</i> 60.00	SN X
15	REAR FLOOR PANEL INSULATION SEAL	1		\$ <i>h</i> 150.00	SN X
16	TAILLAMPS CLIPS	2	\$ 30.00	\$ <i>h</i> 60.00	SN X
				\$ 1,150.00	

C/F \$ 13,505.36

Not Withheld

AERO GARAGE PTE LTD  
BLK 160 SIN MNG DRIVE  
#08-07  
SINGAPORE 575722

B/F \$ 13,505.36

Job Scope	
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGN ALL PARTS	\$ 2,000.00
TO RESPRAY AFFECTED AREAS	\$ 2,000.00
TO TUFFCOAT AFFECTED AREA	\$ 150.00
TO REMOVE / REFIT / REPLACE REAR REVERSE SENSORS AND DISTANCE SETTLING	\$ 250.00
TO REMOVE / REFIT INTERIOR UPHOLSTERY <i>car windscreen</i>	\$ 180.00
TO REMOVE / REFIT AND REPLACE TAILGATE MECHANISM	\$ 180.00
TO CONDUCT WIRING CHECKS	\$ 100.00
	<b>\$ 18,365.36</b>

500  
600  
300  
500  
1200  
600  
150

AH MENG  
HP 91833008

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: