

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 25 Oct 2021

Preliminary Advice

Insured Vehicle No	: SLN5722B	Accident Date	: 13/07/2021
TP Vehicle No	: SMW5426Y	Assignment Date	: 16/07/2021
Make	: TOYOTA VOXY HYBRID	Est. Duration of Repair	: 4
Date of Inspection	: 16/07/2021		
Inspection At	: HENG YAP SENG AUTO SERVICES - (SIN MING DRIVE) (HQ) BLK 160 SIN MING DRIVE, #08-13 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,365.35
Revised Amount	:S\$	3,689.21
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,689.21
 Lump Sum Repair	 :S\$	 2,950.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value (est)	:S\$	135,000.00
COE / PARF Rebate (est)	:S\$	59,384.00
Salvage Value	:S\$	
Margin for Repair	:S\$	75,616.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.