



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR21007724/Kuf3n2 Date: 08/12/2021 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 6277M	Veh. Inspected	SLP 4929T
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/07/21/2028	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	16/07/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA FIT (A)	c.c	1317
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GK31343822	Colour	WHITE
Odometer	19522 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/70 R14	YOKOHAMA	2 mm
L/H Front Tyre	175/70 R14	YOKOHAMA	2 mm
R/H Rear Tyre	175/70 R14	YOKOHAMA	3 mm
L/H Rear Tyre	175/70 R14	YOKOHAMA	3 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/07/2021	Inspection Date	21/07/2021
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	