REF:	Device
ASS. REC. BY: TOTIM CS/CT/2100	7726/Btc Denise
	<u>INMENT</u>
From: Date: 19/7 2021	Veh No: SLS 1874X Yr Regn: 13/9/2017
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD PTP / WS / TP RES / OD RES / EVA / INV / MV	· Truck / Trailer or
To Inspect Vehicle No: SLS 1874 X	Make: Ka Caren 1.7 DCT cc 1685
at Workshop m/s Bifiest Auto	Colour Brews A/C: Insured / Std / NI / NA
of 8 Kaki Bt Ave & Premier # 01-49	Sp.Reading 16(834 T/Radio; Insured / Std / NI / NA
Insured:	Eng/No: D4FDHH109178
Policy No.	C/No: KNAHU8 15 W7188221
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 2>5/45//8
(Policy Condition)	R: 235/45/18 BS WUN EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM! /
Remark: The veh had commenced its N/S O/S	
repair at the time of inspection.	Poor
Bal. or Market Value: 72,00017	R/Bal. 5 mm R/Bal. 5 mm
IDAC Accident Rport: Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	D.O.A. 13/7/2021 D.O.I. 19/7/2021
Est. Repails. 3 Val. Vag or No.	Survey held at Bifrost Auto
Lum Sum.	Des. of Damages : Frt I Rear I O/S I N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS WY Vehicle: IN / OUT	
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	3 most 18/3- Inform My Lim finalise
Range 22,000/2 -2	3,008/2 8/3- 109bru IN UM FINAIRE
Recommended COR is L.	5 \$22,150.60
red: 19470.20;46	% Then lin 7/9(202)
MV 72,000/2 18/03/21-	To Show to curryy
PV 45,135/2	21/7/2021
NV 26,865	18
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
i): Final Report	Resurvey No. of Trip: Survey Fee: Transportation:
Date/Time, File Return to?	
2) Add F6	: Interview (\$) Photos
	: Tech. Invs (\$) Omers
Reputermak:	: Westend (\$
Lump Sum/I.E.I: (%)	TOTAL

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAORE 415875

Tel: +65 64524457 Fax: +65 64524584

Company Reg No: 201929175W

Estimate

Vehicle No: Model and make: SLS1874X Kia Carens

Qty	Spare parts	_	List price 2017
1	Bonnet	\$	693.00 869.00 DD V
1	Bonnet RH hinge	\$	/ 37.00 2 BT./
1	Bonnet LH hinge	\$	V 37.00 5 B
1	Bonnet lock	\$	/ 68.00 JM/
1	Bonnet lock cable (short)	\$	71.00)
1	Bonnet lock cable (long)	\$	156.00 MV
1	Bonnet lock cable bracket	\$	√38.00 BT ✓
1	Bonnet insulator	\$	√113.00 NECV
1	Bonnet stay rod	\$	✓ 27.00 BTV
1	Front bumper	S	627.00 668.00 BRV
1	Front bumper emblem	\$	/32.00)
1	Front bumper RH side retainer	\$	121.00 NECV
1	Front bumper LH side retainer	\$	V21.00
1	Front bumper reinforcement	\$	√ 312.00 BTV.
1	Front bumper lower stiffener	\$	✓ 112.00 BRV
1	Front bumper inner sponge	\$	/ 68.00 BR
1	Front bumper RH fog lamp assy	S	V 212.00 BRV
1	Front bumper RH fog lamp cover	\$	/ 99.00 BR√
1	Front bumper LH fog lamp assy	\$	✓ 212.00 BR ✓
1	Front bumper LH fog lamp cover	\$	✓ 99.00 BRV
1	Front bumper lower grille	\$	/ 159.00 BR /
1	Front bumper centre skid plate garnish	\$	172.00 CRA
1	Front bumper lower lip	\$	√34.00 BRV
1	Front bumper parking sensor wire harness	\$	255.00 GUT
1	Front bumper RH side parking sensor	\$	162.00 150.1
1	Front bumper RH parking sensor	\$	162.00
1	Front bumper LH parking sensor	\$	162.00 Sc
1	Front bumper LH side parking sensor	\$	162.00
4	Front bumper parking sensor holders	\$	16.00 NECV
1	Front bumper top centre rubber strip	\$	√27.00 CUTV
1	Front bumper towing cover	\$	15.00 NDX
1	Front bumper lower cover	\$	140,00 183.00 BR
1	RH headlamp assy	\$	✓ 1,559.00 BR V
1	RH headlamp lower bracket	\$	V 15.00 BR√
1	LH headlamp assy	\$	1,559.00 BRV
1	LH headlamp lower bracket	\$	15.00 BRV
1	Support panel	\$	525.90 636.00 BRV
1	Support panel top cover	S	148.00 BRV
1	Front grille	\$	√269.00 BRV
1	Front RH fender	\$	✓ 325.00 DD ✓
1	Front RH fender splash shield	\$	✓ 78.00 T N ✓

1	Front LH fender	\$ \(\sqrt{325.00 DP \(} \)
1	Front LH fender splash shield	\$ 78.00 TN V
1	Aircon condenser	\$ \(\sqrt{687.00} \) \(\sqrt{0} \)
1	Aircon condenser RH side guard	\$ \(\square 18.00 \) \(\lambda \)
1	Aircon condenser LH side guard	\$ \(\square 18.00 \)
1	Aircon condenser suction pipe	\$ \(\sqrt{273.00} \) BT \(
1	Aircon condenser discharge pipe	\$ \(\sqrt{331.00} \)
1	Radiator	\$ \(\sqrt{703.00} \) \(\nabla
1	Radiator fan assy	\$ / 533.00 BRV
1	Radiator upper hose	\$ \(74.00 \cdot \c
1	Radiator lower hose	\$ 83.00 \int \alpha \tag{4}
1	Radiator spare tank	\$ \(\sqrt{38.00} \) \(\nabla \)
1	Turbo intercooler	\$ 1032.40 1,183.00 DDV
1	Turbo intercooler inlet pipe	\$ 193.00 BTV
1	Front horn	\$ 54.00 SC \sqrt{
1	Air duct	\$ \(\sqrt{66.00 ?\alpha1} \times
1	Air duct lower adapter	\$ \(\square 35.00 ? BR \square
1	Air cleaner assy	\$ 252.00 ? BR \sqrt{
1	Air cleaner hose	\$ \(\sqrt{32.00 ? DD }
1	Air resonator box	\$ \ \ \ 139.00 ? CUTV
1	Air flow sensor	\$ 397.00 ? BR
1	Intake manifold	\$ 1,183.00 ? BR
1	Engine top cover	\$ 128.00 ? NDX
1	Engine dip sticker	s 19.00 ? № D×
1	Front wiper garnish	\$ 202.00 ? \qquad \qq \q
1	Front windscreen glass	S 955.00 2 NDX
1	Front windscreen glass rubber moulding	s 94.00 ? NNX
1	Dashboard	s 984.00 ? ND X
1	Passenger airbag	\$ 1,070.00 ND X
1	Steering airbag	\$ 1317 or 1.730.00 Activated
1	Steering clock sensor	150.00 ? NDX
1	Airbag control unit	\$ 933.00 Activated
1	Airbag sensor	\$ 131.00 Driver side
1	Passenger seat belt	\$ \(\sigma 553.00 \) \(\sigma \sigma \sigma \tag{7553.00} \)
1	Passenger seat belt tensioner	The
2		\$ \(\frac{164.00}{} \)
1	Driver seat belt	\$ \(\sqrt{64.00} \) \(\sqrt{553.00} \) \(\sqrt{64.00} \)
1	Driver seat belt Driver seat belt tensioner	\$ \sqrt{553.00} Activated \$\\ 164.00 \]
		5 (104.00)
	Driver seat belt tensioner	\$ \text{164.00} \\ \text{367.00} \text{165} \text{165} \text{167.00} \text{165} \text{167.00} \text{165} \text{167.00} \te
1 1	Driver seat belt tensioner Rear RH seat belt	\$ 367.00 \$ 367.00
1 1 1	Driver seat belt tensioner Rear RH seat belt Rear LH seat belt	\$ 367.00 \$ 367.00
1 1 1	Driver seat belt tensioner Rear RH seat belt Rear LH seat belt Tailgate	$\begin{array}{cccccccccccccccccccccccccccccccccccc$
1 1 1 1	Driver seat belt tensioner Rear RH seat belt Rear LH seat belt Tailgate Tailgate "CRDI" emblem	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$
1 1 1 1 1	Driver seat belt tensioner Rear RH seat belt Rear LH seat belt Tailgate Tailgate "CRDI" emblem Tailgate "Carens" emblem	\$ $\frac{367.00}{367.00}$ NDX \$ $\frac{367.00}{1,218.00}$ DD \checkmark \$ 29.00 NECV \$ 36.00 NECV
1 1 1 1 1 1	Driver seat belt tensioner Rear RH seat belt Rear LH seat belt Tailgate Tailgate "CRDI" emblem Tailgate "Carens" emblem Tailgate lock	\$ $\frac{367.00}{367.00}$ NDX \$ $\frac{367.00}{367.00}$ NDX \$ $\frac{1,218.00}{36.00}$ DD \checkmark \$ $\frac{29.00}{36.00}$ NECV \$ $\frac{109.00}{31.00}$ ND \checkmark
1 1 1 1 1 1 1	Driver seat belt tensioner Rear RH seat belt Rear LH seat belt Tailgate Tailgate "CRDI" emblem Tailgate "Carens" emblem Tailgate lock Tailgate lock catch	\$ $\frac{367.00}{367.00}$ NDX \$ $\frac{367.00}{367.00}$ NDX \$ $\frac{1,218.00}{36.00}$ DD \checkmark \$ $\frac{29.00}{36.00}$ NECV \$ $\frac{109.00}{31.00}$ ND \checkmark
1 1 1 1 1 1 1 1	Driver seat belt tensioner Rear RH seat belt Rear LH seat belt Tailgate Tailgate "CRDI" emblem Tailgate "Carens" emblem Tailgate lock Tailgate lock catch Tailgate inner trim board	\$ $\frac{367.00}{367.00}$ NDX \$ $\frac{367.00}{367.00}$ NDX \$ $\frac{29.00}{36.00}$ NECV \$ $\frac{29.00}{36.00}$ NECV \$ $\frac{31.00}{378.00}$ ND X \$ $\frac{378.00}{378.00}$ BR V
1 1 1 1 1 1 1 1 1	Driver seat belt tensioner Rear RH seat belt Rear LH seat belt Tailgate Tailgate "CRDI" emblem Tailgate "Carens" emblem Tailgate lock Tailgate lock catch Tailgate inner trim board Tailgate weatherstrip	\$ 1088.60 \\\\ \frac{367.00}{367.00} \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
1 1 1 1 1 1 1 1 1 1	Driver seat belt tensioner Rear RH seat belt Rear LH seat belt Tailgate Tailgate "CRDI" emblem Tailgate "Carens" emblem Tailgate lock Tailgate lock catch Tailgate inner trim board Tailgate weatherstrip Rear bumper top Rear bumpe lower	\$ 1088.60 \\\\ \frac{367.00}{367.00} \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
1 1 1 1 1 1 1 1 1 1	Driver seat belt tensioner Rear RH seat belt Rear LH seat belt Tailgate Tailgate "CRDI" emblem Tailgate "Carens" emblem Tailgate lock Tailgate lock Tailgate inner trim board Tailgate weatherstrip Rear bumper top	\$ \\ \frac{367.00}{367.00} \\ \text{ND} \times \\ \frac{367.00}{367.00} \\ \text{ND} \times \\ \frac{29.00}{36.00} \\ \text{NECV} \\ \text{S} \\ \frac{31.00}{378.00} \\ \text{BR} \times \\ \frac{378.00}{576.00} \\ \text{BR} \times \\ \frac{576.00}{576.00} \\ \text{BR} \times \\ \frac{131.00}{576.00} \\ \text{BR} \times \\ \frac{131.00}{576.00} \\ \text{BR} \times \\ \end{array}
1 1 1 1 1 1 1 1 1 1 1 1	Driver seat belt tensioner Rear RH seat belt Rear LH seat belt Tailgate Tailgate "CRDI" emblem Tailgate "Carens" emblem Tailgate lock Tailgate lock Tailgate inner trim board Tailgate weatherstrip Rear bumper top Rear bumper cenre skid plate garnish	\$ \\ \frac{367.00}{367.00} \\ \n
1 1 1 1 1 1 1 1 1 1 1 1 1	Driver seat belt tensioner Rear RH seat belt Rear LH seat belt Tailgate Tailgate "CRDI" emblem Tailgate "Carens" emblem Tailgate lock Tailgate lock Tailgate lock catch Tailgate inner trim board Tailgate weatherstrip Rear bumper top Rear bumper cenre skid plate garnish Rear bumper RH side reverse sensor	\$ \\ \frac{367.00}{367.00} \\ \nambda \times \\ \frac{367.00}{367.00} \\ \nambda \times \\ \frac{29.00}{36.00} \\ \nambda \times \\ \frac{29.00}{36.00} \\ \nambda \times \\ \frac{31.00}{378.00} \\ \nambda \times \\ \nambda \\ \namb
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Driver seat belt tensioner Rear RH seat belt Rear LH seat belt Tailgate Tailgate "CRDI" emblem Tailgate "Carens" emblem Tailgate lock Tailgate lock Tailgate lock catch Tailgate inner trim board Tailgate weatherstrip Rear bumper top Rear bumper cenre skid plate garnish Rear bumper RH side reverse sensor Rear bumper RH reverse sesnor	\$ \\ \frac{367.00}{367.00} \\ \text{NDX} \\ \$ \\ \frac{367.00}{367.00} \\ \text{NDX} \\ \$ \\ \frac{29.00}{36.00} \\ \text{NECV} \\ \$ \\ \frac{109.00}{36.00} \\ \text{ND} \text{X} \\ \$ \\ \frac{109.00}{378.00} \\ \text{BR} \times \\ \$ \\ \frac{378.00}{576.00} \\ \text{BR} \times \\ \$ \\ \frac{131.00}{576.00} \\ \text{BR} \times \\ \$ \\ \frac{179.00}{179.00} \\ \text{NDX} \\ \$ \\ \frac{162.00}{50.00} \\ \text{SCV} \\ \$ \\ \frac{162.00}{50.00} \\ \text{SCV} \\ \$ \\ \frac{162.00}{50.00} \\ \text{SCV} \\

4	Rear bumper reverse sensor holders	\$	V16.00 NEC
1	Rear bumper reverse sensor wire harness	\$	251.00 CUTV
1	Rear bumper reinforcement	\$	√ 367.00 BIV
1	Rear bumper reinforcement RH bracket	\$	159.00 L pt
1	Rear bumper reinforcement LH bracket	\$	V 159.00 D V
1	Rear bumper RH bracket	\$	√ 16.00)
1	Rear bumper LH bracket	\$	V16.00 NECV
1	Rear bumper RH lower bracket	\$	√16.00 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
1	Rear bumper LH lower bracket	\$	16.00
1	Rear bumper centre bracket	\$	V30.00 NECV
1	Rear bumper RH fog lamp	\$	√ 116.00 \ E P ✓
1	Rear bumper LH fog lamp	\$	V 116.00
1	Rear bumper RH side retainer	\$	V 25.00 ? NECV
1	Rear bumper LH side retainer	\$	25.00
1	Rear bumper towing cover	\$	✓ 15.00 BR ✓
1	End panel		453.00 543.00 DDV
1	End lower panel	\$	188.00 ? NSX
1	End panel inner garnish	\$	√ 78.00 BRV
1	RH taillamp assy	\$	✓ 428.00 ?BR ✓
1	LH taillamp assy	\$	√ 428.00 ? BRV
1	Exhaust silencer	\$	√ 756.00 B7 √
2	Exhaust silencer rubber mountings	\$	23.00 68.00 NECV,
1	Exhaust silencer gasket	\$	√ 9.00 NEC √
1	Exhaust centre pipe	\$	553.00 NDX
1	Exhaust centre pipe gasket	\$	9.00 NDX
1	Rear compartment panel	\$	631.00 7 NDX
1	Rear compartment trim box	\$	223.00 7 NPX
1	Rear RH fender inner trim board	\$	411.00 ? ND X
1	Rear LH fender inner trim board	\$	411.00 ? NDX
			, he V
		\$	34,078.00
	-10	% \$	3,407.80
		\$	30,670.20
		-	

Qty Spare parts	Special Nett price
1set Bonnet insulator clips	\$ 7 3 60 70-01

1set	Bonnet insulator clips	\$ 30:00	70.00 NECV
1set	Front bumper clips	\$ 30.00	70.00 NECV
1set	Front RH fender splash shield clips	\$	60.00 NN X
1set	Front LH fender splash shield clips	\$	60.00 NNX
1	Radiator coolant	\$ 30:00	50.00 NECV
1set	Support panel top cover clips	\$ 30.00	50.00 NECV
1	Front windscreen glass sealant	\$	70.00)
1	Front windscreen glass inner seal	\$	50.00 7 NNX
1	Tailgate "Club Carens" sticker	\$ 20.00	50.00 NEC
1	Tailgate windscreen glass sealant	\$	70-00
1	Tailgate windscreen glass inner seal	\$	50.00 (NN ×
1	Tailgate inner trim board clips	\$	60.00 NNV
1	Tailgate reverse camera	\$	650.00 ND
1	Rear bumper clips	\$ 30.00	70.00 NECV

1 Rear bumper top chrome plate 1set Rear fender RH inner board clips 1set Rear fender LH inner board clips 1 End panel joint sealant 1 Rear floor compartment panel joint sealant	\$ \$ \$ \$	30.00	320.00 PDV 60.00 FNNY 60.00 PECV 80.00 NNX
Labour and painting			
Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels (front)	\$	1000.00	1,500.00
Spray painting on affected panels (front)	\$	800.00	1,400.00
Check wiring and lighting system (front)	\$	30.00	80.00
Apply rust coating chemical on affected panels	\$	40.00	150.00
Remove and replace aircon condenser, pipes and hoses to assist repair. To refill aircon gas	\$	60-00	200.00
Remove and replace radiator assy, pipes, hoses and fan assy to assist repair. To refill coolant	\$	60 =00	200.00
Remove and replace intake manifold and all attachments to assist repair	\$	50.00	150.00
Remove and replace front windscreen glass to assist repair	\$		180.00 NNX
Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels (rear)	\$	600.00	1,400.00
Spray painting on affected panels (rear)	\$	600.00	1,200.00
Check wiring and lighting system (rear)	\$		X44 00.08
Remove and reinstall tailgate windscreen glass to assist repair	\$	120.00	200.00
Remove and replace tailgate inner parts to new tailgate	\$	80.00	150.00
Remove and replace tailgate reverse camera to assist repair	\$		-80.00 NN X
Remove and replace rear inner trims, garnish, boards and mat to assist repair	\$		350.00 NNX
Remove and replace exhaust silence, centre pipe and rubber mountings to assist repair	\$	120:00	220.00
Remove and replace steering airbag, passenger airbag, sensor and all attachment to assist repair	\$	230.00	480.00
Remove and replace dashboard and all attachments to assist repair	\$		300.00 NNX
Remove and replace front, rear seat belts and tensioner to assist repair	\$	80.00	150.00

Remove and reinstall front and rear sest belts garnish to assist repair

100.00 NN

Reset and diagnose airbag system and all fault codes

\$ 190.00 380.00 NECV

Total: \$ 41,620.20

Survey Resurvey
19/7/2021 -397/2021
Talin Talin
Win 14 Hohrs
1300hrs

Parts 23,337.18 SN 368.00 Labour 4010.00 27,715.18

Cump sum repair Repair days 18

@ 20% 5,543.04 22,172.14

LS 22,150/2

741m Mmi 7/9/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date of Accident	: 13/1 2021 Accident Time: 5:50 PM (24-HR-FORMAT)
Accident Place	: PIE (TUGS) before Steven Exy
Vehicle Reg, No (Car plate No.)	: SLS1874 X Vehicle Make/Model: FIG Carens
Insurance Company	ALE Policy No. 17000 50167 -0.
Name of Registered Owner	: Company/Individual SCHINOIS LIMONSINES & TRAVEL
ID of Registered Owner	: Co Reg No: 5330 8848L Owner's NRIC No:
	: Co Contact No: Owner's Contact No:
DRIVER'S Name	: EWER Lye Hock DRIVER'S NRIC No: S7435703B
DRIVER'S Date of Birth	: 11/11/1974 DRIVER'S License Pass Date 20/6/1991
Relationship bet. Owner & Driver	: Spouse \ Parents \Children\ Sibling \ Employee\ Others: Pla4x
DRIVER'S Address	: 217 marsiling (Asmy #03-89 S(73=217)
DRIVER'S Contact No./ Alt No.	:1) 96575858 2)
DRIVER'S Occupation	: INDOOR \OUTDOOR (eg. working inside or outside of an ofc)
Email Address	: Alan ower 6 gnail.com
Weather & Road Surface	: CLEAR & DRY \ RAIN(N) & WET \AFTER RAIN & WET
Reporting Type	: Reporting Only \ Claim Other Party \ Claim Own Insurance
Was there any video Captured by car	iver):Name & Gender; ce? YES \ NO camera: YES \ NO being used at the time of accident: Private use \ Work purpose jured person) P(\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Other	Party Driver's Particulars (if any)
Vehicle Reg No: SLX 6757 (B)	Vehicle Reg No: SMk 2646L
Vehicle Make\Model:	Vehicle Make\Model:
Name DRIVER:	Name DRIVER:
IC No. DRIVER:	IC No. DRIVER:
DRIVER'S Contact & add;	

SKE 18365

Describe Gircumstances of the Accident travelling along PR Sha Tuas. The vinicle Slowed Stop. I A151 Saddulg, MAr. Cansid my th Gt Vehille to WI UNI 44 mehlele front gol down nowly nea/1211 CGGS

Declaration

IWe declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

SGCARMART.COM

Login Sign up

New Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Test Drive Now

Resources



Post an Advertisement Sell it yourself! Advertise it at just \$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2014 Honda CR-Z Hybrid 1.5A At \$30800.



Direct Owner StarAd

VALUE FOR MONEY VALUE FOR TIME A PEACE OF MIND HOTLINE: 6741 9997 view our cars

Browse by Category

3 vehicles

Kia Carens 1.7

Model

Price Depreciation

Any

2017

Eng Cap

Mileage

Veh Type

MPV

Available

PREMIUM AD

Available

Search Selection

Kia Carens 1 7

\$74,800

\$10,390 /yr

16-Nov-2017

26-Jul-2017

1,685 cc

1.685 cc

Any

53,000 km

57,890 km

Sort by Reg. Date

MPV Available

20 results/page

Fuel Type: Diesel (Euro 5 Engine and Above)

PHV Full Loan Welcome! Agent Serviced, Under Agent Warranty, Brand New Paintwork! Low Millage Diesel Unit! Perfect Condition With No Repairs Needed! Full Loan Interest Rates Available From 3.xx% Only! Attractive Monthly Installment At \$12xx For Full Loan!..

Precise Auto Trading Pte Ltd

Posted: 10-Jul-2021 Tags: 2017 Kia Carens, Kia Carens, Kia, Carens

Kia Carens Diesel 1.7A

Kia Carens Diesel 1.7A SX

\$73,888 Fuel Type: Diesel (Euro 5 Engine and Above)

1 Lady Owner, High Spec SX Model, Fully Serviced By Agent Since Day 1, Agent Warranty Till July 2022 And 10 Years Engine Warranty, Still Feel Like New Car. 100% Accident Free! Bank Loan & In-house Full Loan At Lowest Rates. Call Us Now For Viewing B...

\$10,750 /yr

Posted: 11-Jul-2021 Tags: 2017 Kia Carens, Kia Carens, Kia, Carens

Kia Carens Diesel 1,7A SX

\$65,800

\$9,990 /vr

11-Jan-2017

1,685 cc

MPV

Available

PREMIUM AD

Sunroof

Fuel Type: Diesel (Euro 5 Engine and Above) 1 Owner, Car Is Fully Service By Agent, 10 Years Engine Warranty, All Wear And Tear Parts Replaced By C&C, Still Under Unlimited Mileage Warranty By Agent, Trade-in Or Consign Your Current Vehicle! High In-house And Bank Financing Available! Call/WhatsApp F.

Monster Motors Pte Ltd

Posted: 03-Jul-2021 Tags: 2017 Kia Carens, Kia Carens, Kia, Carens

Save this search criteria, to get email alerts whenever a match is found.

Model

Eng Cap

Mileage

Veh Type

For old advertisements, view Expired ads

20 v results/page

Home | New Cars | Used Cars | Rental Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Kia Carens 1.7, Kia Carens 1.7 Singapore, used Kia Carens 1.7 Singapore, used Kia Carens 1.7, used vehicles Singapore or even buy used Kia Carens 1.7 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2021 sgCarMart, Singapore. All rights reserved.