ASS. REC. BY: Tay film 1 ..... (C4 | A1 9 21007 728/71793 ASSIGNMENT Veh No: SHOUSEP Yr Regn: 2017 Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / From: Estimated Cost: ODVTP/WS/TP RES/OD RES/EVA/INV/MV Truck / Trailer or To Inspect Vehicle No: c.c 1582 Make: at Workshop m/s Colour A/C: Insured / Std / NI / NA Sp.Reading T/Radio; Insured / Std / NI / NA Insured: Eng/No: Policy No. C/No: Gen. Cond: Good / Fair / Poor / Burnt Claims No. Steering: Inorder / Jammed / Leaked / Burnt or Sum Insured: Brake: Inorder / Jammed / Leaked / Burnt or (Client's Record) Modi: Ni / S/Rim / STD A/Rim or Make of Veh: Tyre Size: (Policy Condition) Remark: The veh had commenced its N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / repair at the time of inspection. TOYO/YOKO or Marris -Bal. or Market Value: Front Rear Consistent?: Yes or No IDAC Accident Rport: R/Bal. R/Bal. mm mm Consistent?: Yes or No L/Bal. L/Bal. GIA / PR Seen: mm Res.: Yes or No D.O.A. D.O.I. Est. Repairs: days 3 Val.: Yes or No Lum Sum: Survey held at Des. of Damages /. Frt / Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Action / Instruction Date / Time Date/Time, File Pass to? : Preli. Report Days Of Repair: Resurvey No. of Trip: : Final Report Survey Fee: Date/Time, File Return to? Transportation: Add Fee: : Site Insp (\$ \_S + RS. SI : Interview (\$ Photos Reper Formar: : Tech. Invs (\$ Lump Sum / LE.E. Co : Weellend (\$ TOTAL

## PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 \$INGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

16-Jul-21

| ESTIMATE REPAIR BILL FOR HYUNDAI | 130 (A) REGN NO: SHD 1138 P |
|----------------------------------|-----------------------------|
|----------------------------------|-----------------------------|

| ESTIMALE                         | REPAIR BILL FOR ITTOMBAL   | 100 (71)            | 100000000000000000000000000000000000000   |               |  |
|----------------------------------|--|---------------------|---|---------------|--|
| ACTORIO DE PROTEGO DE            |  |                     |   | \$            | 811.11                                     |
| 1 pc                             | Front bumper   |                     |   | \$            | 514.02                                     |
| 1 pc                             | Front o/s fender Front bumper n/s & o/s side brace   | ket@9               | 332.51  | \$ 1          | / 5× 65.02 / 5 /                           |
| 2 pcs                            |  | not w               | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,   | \$            | 840.90 🗶                                   |
| 1 pc                             | Front o/s fog lamp   |                     |   | \$            | 566.46                                     |
| 1 pc                             | Bonnet grille  |                     |   | \$            | 324.79 ent_                                |
| 1 pc                             | Bonnet grille - piece moulding   |                     |   | \$            | 27.80 7                                    |
| 1 pc                             | Front bumper emblem  |                     |   | \$            | 60.10 auf                                  |
| 1 pc                             | Front bumper tow cap   |                     |   | \$            | 158.76 X                                   |
| 1 pc                             | Front bumper lip   |                     |   | \$            | 1,531.57                                   |
| 1 pc                             | Front o/s head lamp  |                     |   | \$            | 4,900.53                                   |
|                                  |  |                     | Less 20%  | \$            | 980.11                                     |
|                                  |  |                     |   | \$            | 3,920.42                                   |
|                                  |  |                     |   |               |  |
| S/NETT  1 set 1 pc 1 set 1 pc    | Front bumper clips Front n/s fender sticker Front n/s fender inner shield clip Front no. plate   | ps                  | LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" No illegal modification(s) is allowed Supplementary item(s) must be resurveyed air is subject to final approval from Insurance Confirmation | nd<br>Pany \$ | 48.00 3 □<br>30.00 ×<br>28.00 ×<br>50.00 × |
|                                  | Sundry   |                     | Signature:  | \$            | 50.00 ^                                    |
|                                  | To check front n/s wheel alignr  | nent                | Date:   | \$            | 80.00 ×                                    |
|                                  | To labour charge for dismantle damaged parts. Including known reshape and adjust of the sam  | and rer<br>k-out, s | new the accident<br>traighten, repair,  | \$            | 200<br>650.00                              |
|                                  | To putty and spray painting on   | front bu            | ımper, bonnet grille  | \$            | 600.00                                     |
| To apply rustproofing on the rep |  |                     |   | \$            | 120.00 ×                                   |
|                                  | · o alth. A section of the section o |                     |   | \$            | 5,576.42                                   |
|                                  |  |                     | $\mathcal{T}_{\mathbf{a}}$  | Ihr           | 97495749                                   |
|                                  | ALL THE BEDAIR COSTS A   | RE SUE              | RIFCTED TO GST )  | 101           | 1/12/71 1                                  |

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tauphin 97495749 WP' 26/7/71 e 1540 2 den 3 1/5 Nossy Agr report fauphin O Hellaupen

Text size +

## **Enquire Vehicle Registration Details**

Owner Particulars

NRIC/Passport/Company Cert 200304975H

No.:

Owner ID Type:

Company

Owner Name:

PREMIER TAXIS PTE. LTD.

Registered Address:

23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443

Mailing Address:

Birth Date:

Vehicle Particulars

Vehicle No.:

SHD1138P

Previous Vehicle No.:

Effective Date of Ownership:

25 Jan 2017 25 Jan 2017

Original Regn Date:

25 Jan 2017

Registration Date: Year of Manufacture:

2016

Vehicle Type:

Public Transport Taxi (Motor Car)

Vehicle Scheme:

Taxi (Company)

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

HYUNDAI

Vehicle Make:

130 GDH 1.6 TCI 5DR DCT

Vehicle Model: Primary Colour:

Silver

Secondary Colour:

Passenger Capacity:

4

Chassis No .:

TMAD281UVHJ119093 D4FBGZ096078

Engine No.:

Engine Capacity/Power Rating:

1582 cc / -

Maximum Power Output:

100.0 kW (134 bhp)

Propellant:

Diesel

Max Unladen Weight:

1496 kg 1940 kg

Maximum Laden Weight:

\$20,830.00

Open Market Value: PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

24 Jan 2025

Minimum PARF Benefit:

\$8,197.00

No. of Transfers:

IU Label No .:

1050703165

COE No .:

2017012501003882H

COE Expiry Date:

24 Jan 2025

COE Category:

A - Car (up to 1600cc & 97kW (130bhp))

COE Registration Category:

A - Car (up to 1600cc & 97kW (130bhp))

## Vehicle Registration Detail Information

Quota Premium (QP) / Prevailing Quota Premium:

-/\$50,645.00

PQP Paid:

\$40,516.00

QP (Regn Cat):

OPC Cash Rebate Eligibility:

Vehicle Lifespan Expiry Date:

No

QP during COE Bidding

Exercise: Additional Registration Fee

First \$20,000.00 (100%), next \$830.00 (140%)

Actual ARF Paid:

\$13,662.00

24 Jan 2025

CO2 Emission:

127.00 (g/km)

Message:

CEVS Rebate Utilised Amount: \$7,500.00 The vehicle will be de-registered upon expiry of its 8-year COE on 24 Jan 2025. No further

renewal will be allowed. This is a public service vehicle.

OK

Print

Save as PDF

Land ramport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | Privacy Statement | Terms of Use | Disclaimer | Rate the Website | Rate this e-Service