



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78
SHENTON WAY #07-16
SINGAPORE 079120

Contact : -

Fax No. : 6880 4838

*Not Authorized
L1 Imp \$950/hr
Resurvey After Paint
2 days*

Estimate : QUOT202107-000508(00)

Date : 16/07/2021

Vehicle No. : SKS8035S

Make/Model : TOYOTA CAMRY 2.0 AUTO

Mileage (km) : 0

Chassis No. : MR053BK5104010572

Accident Date : 15/07/2021 00:00:00

Claim No. : ER7667B

Reference : JO202107-0649

Policy No. : SP2000384814-01

| S/No | Particular | Quantity | Unit Price | Amount S\$ |
|------------------------|---|----------|------------|------------|
| LIST ITEMS : | | | | |
| 1 | Front bumper <i>522-10</i> | 1.0 | 596.90 | 596.90 ✓ |
| 2 | Front bumper retainer | 2.0 | 100.40 | 200.80 ✓ |
| 3 | Front bumper sponge | 1.0 | 102.50 | 102.50 ✗ |
| 4 | Front bumper reinforcement | 1.0 | 399.50 | 399.50 ✗ |
| 5 | LH foglamp | 1.0 | 310.40 | 310.40 ✗ |
| 6 | LH foglamp cover | 1.0 | 68.20 | 68.20 ✗ |
| 7 | Washer tank | 1.0 | 219.10 | 219.10 ✗ |
| 8 | Washer motor | 1.0 | 291.60 | 291.60 ✗ |
| 9 | LH headlamp | 1.0 | 1,294.60 | 1,294.60 ✗ |
| 10 | LH parking sensor cap | 1.0 | 20.30 | 20.30 ✗ |
| 11 | Front LH fender innershield | 1.0 | 200.10 | 200.10 ✗ |
| 12 | Front LH fender innershield clip | 8.0 | 2.80 | 22.40 ✗ |
| 13 | Bumper clip | 10.0 | 4.50 | 45.00 ✓ |
| List Total : | | | | 3,771.40 |
| 25% Discount S\$ | | | | 942.82 |
| | | | | 2,828.58 |
| SPECIAL NET : | | | | |
| 1 | LH parking sensor <i>245</i> | 1.0 | 392.80 | 392.80 ✓ |
| SPECIAL NET Total S\$: | | | | 392.80 |
| LABOUR : | | | | |
| | - To check wiring and lighting | 1.0 | 60.00 | 60.00 |
| | -To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts | 1.0 | 400.00 | 400.00 |
| | - Spray painting on affected & replace parts | 1.0 | 500.00 | 500.00 |
| | | | | 960.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tet 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78
SHENTON WAY #07-16
SINGAPORE 079120

Contact : -

Fax No. : 6880 4838

Estimate : QUOT202107-000508(00)

Date : 16/07/2021

Vehicle No. : SKS8035S

Make/Model : TOYOTA CAMRY 2.0 AUTO

Mileage (km) : 0

Chassis No. : MR053BK5104010572

Accident Date : 15/07/2021 00:00:00

Claim No. : ER7667B

Reference : JO202107-0649

Policy No. : SP2000384814-01

| S/No | Particular | Quantity | Unit Price | Amount S\$ |
|------|------------|----------|------------|------------|
|------|------------|----------|------------|------------|

E. & O.E.

Total S\$: 4,181.38

GST 7% S\$: 292.70

Amount Due S\$: 4,474.08

for CITY AUTO PTE LTD