



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN.: MOTOR CLAIMS FAX:		NAME: ADDRESS: TEL:		WIP: 38075 EXCESS: DATE: 13-Jul-21			
VEH NO:	SGL1173G	DATE IN:		CONTACT PERSON:	DEREK		
CHASSIS NO:	JM6GJ1072G0240930	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM		
MODEL:	M6	DATE REG.:	24-Jun-16	POLICY NO.:			
NATURE OF WORKS							
Parts Description							
NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	REAR BUMPER / <i>nk</i>	MGJR9-50-221ABB	1	/			\$ 1,231.50
2	BRACKET CENTER RR BUMPER <i>X nn</i>	MKD53-50-251	1				\$ 5.40
3	REINF REAR BUMPER <i>X nn</i>	MGHK1-50-260	1				\$ 538.30
4	GROMMET, SCREW <i>nk</i>	MH260-50-841	4	/			\$ 12.00
5	FASTENER <i>nk</i>	MB45A-56-146A	6	/			\$ 18.00
6	COVER TOWING LH <i>mit</i>	MG4YL-50-EL1 27	1	/			\$ 24.90
7	COVER TOWING RH <i>mit</i>	MGJR9-50-EK1A27	1	/			\$ 24.90
8	REFLECTOR LH <i>X nn</i>	MD350-51-5L0E	1				\$ 53.00
9	REFLECTOR RH <i>X nn</i>	MD350-51-5M0E	1				\$ 53.00
10	RETAINER LH <i>X nn</i>	MGJR9-50-2J1	1				\$ 41.00
11	RETAINER RH <i>X nn</i>	MGJR9-50-2H1	1				\$ 41.00
12	GASKET TAIL LAMP LH <i>nk</i>	MGHK1-51-163	1	/			\$ 29.10
13	GASKET TAIL LAMP RH <i>nk</i>	MGHK1-51-153	1	/			\$ 29.10
TOTAL PARTS							\$ 2,101.20
TOTAL PARTS COST							\$ 2,101.20
SUPPLEMENTARY							
NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1							
2							
3							
TOTAL PARTS							\$
TOTAL PARTS COST							\$
Labour Description							

		TO REPLACE REAR BUMPER AND REAR INFORCEMENT. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS.	660	\$ 1,100.00
		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND ALL AREAS AFFECTED BY THE ACCIDENTS.	630	\$ 1,575.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	330	\$ 660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 200.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 250.00
6	MZ-BR-SUNDRI	SUNDRIES.	20	\$ 50.00
			TOTAL LABOUR	\$ - \$ 3,835.00
			TOTAL PARTS	\$ - \$ 2,101.20
			TOTAL	\$ - \$ 5,936.20
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ - \$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

SUPPLEMENTARY LABOUR DESCRIPTION

1	#N/A			
2	#N/A			
			TOTAL LABOUR	\$ - \$ -
			TOTAL PARTS	\$ - \$ -
			TOTAL	\$ - \$ -
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ - \$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

Steve (CLKK) ML AL
8372 8813 3 4's
P/P
My BLy
21/7/21, 2:30pm

TRANS EUROKARS PTE LTD

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

- Ask Auto Consultant's hence notify the Repairer of the following:
- To resurvey before start spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Authorised Signature