



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN. : MOTOR CLAIMS FAX :		NAME : ADDRESS : TEL :		WIP : 38075 EXCESS : DATE: 28-Sep-21			
VEH NO :	SGL1173G	DATE IN :		CONTACT PERSON :	DEREK		
CHASSIS NO :	JM6GJ1072G0240930	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM		
MODEL :	M6	DATE REG.:	24-Jun-16	POLICY NO. :			
<u>NATURE OF WORKS</u>							
<u>Parts Description</u>							
NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	REAR BUMPER	MGJR9-50-221ABB	1			\$ 1,231.50	\$ 1,231.50
2	BRACKET CENTER RR BUMPER	MKD53-50-251	1				\$ 5.40
3	REINF REAR BUMPER	MGHK1-50-260	1				\$ 538.30
4	GROMMET,SCREW	MH260-50-841	4			\$ 12.00	\$ 12.00
5	FASTENER	MB45A-56-146A	6			\$ 18.00	\$ 18.00
6	COVER TOWING LH	MG4YL-50-EL1 27	1			\$ 24.90	\$ 24.90
7	COVERT TOWING RH	MGJR9-50-EK1A27	1			\$ 24.90	\$ 24.90
8	REFLECTOR LH	MD350-51-5L0E	1				\$ 53.00
9	REFLECTOR RH	MD350-51-5M0E	1				\$ 53.00
10	RETAINER LH	MGJR9-50-2J1	1				\$ 41.00
11	RETAINER RH	MGJR9-50-2H1	1				\$ 41.00
12	GASKET TAIL LAMP LH	MGHK1-51-163	1			\$ 29.10	\$ 29.10
13	GASKET TAIL LAMP RH	MGHK1-51-153	1			\$ 29.10	\$ 29.10
TOTAL PARTS						\$ 1,369.50	\$ 2,101.20
TOTAL PARTS COST						\$ 1,369.50	\$ 2,101.20
<u>Labour Description</u>							
1		TO REPLACE REAR BUMPER AND REAR INFORCEMENT. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS.				\$ 660.00	\$ 1,100.00
2		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND ALL AREAS AFFECTED BY THE ACCIDENTS.				\$ 630.00	\$ 1,575.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.				\$ 330.00	\$ 660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				\$ 200.00	\$ 200.00

5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 250.00	\$ 250.00
6	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 50.00
			TOTAL LABOUR	\$ 2,090.00 \$ 3,835.00
			TOTAL PARTS	\$ 1,369.50 \$ 2,101.20
			TOTAL	\$ 3,459.50 \$ 5,936.20
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 3,459.50 \$ 5,936.20
			GST 7%	\$ 242.17 \$ 415.53
			GRAND TOTAL	\$ 3,701.67 \$ 6,351.73

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature