

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile				
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21007763/Auf3n2
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	17/08/2021
			Code	: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SCM 4515B	Veh. Inspected	SJF 9331K
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10010968/CD	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	19/07/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MR053HY9305067269	Colour	GREY
	Odometer	341680 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	NEXEN	6 mm
	L/H Front Tyre	185/60 R15	NEXEN	6 mm
	R/H Rear Tyre	185/60 R15	NEXEN	6 mm
	L/H Rear Tyre	185/60 R15	NEXEN	6 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	16/07/2021	Inspection Date	21/07/2021
	Survey held at	NEW HOCK TECK MOTOR PTE	LTD	
	1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	p. Estimate Days of Repair			

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: