

Labour Charges For Rear Portion

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

Auto & General Southeast Asia (SEA)
190 Clemenceau Ave, #03-01
Singapore Shopping Centre
Singapore (239924)
ATTN: MOTOR CLAIM DEPARTMENT

Not Notwithstanding
11/2/2050h
Resurvey After Repair
-4 days

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SLR8745U
MODEL : SUBARU FORESTER
POLICY NO :
CHASSIS NO : JF1SJGK85JG097810
YEAR OF MANUFACTURE : 2017
DATE / TIME OF ACCIDENT: 07/07/2021 Time: 1705Hrs at TESSENSOHN ROAD TOWARDS BALESTIE
THIRD PARTY VEHICLE NO: SBA73K

Date: 13/07/2021
Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle:-

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
1 REAR BUMPER	1	S\$ 600.00	As	S\$ 600.00 ✓
2 TAIL GATE	1	1,192.00	n	1,192.00 X
3 REAR BUMPER CLIPS	4	5.10	n	20.40 ✓
4 RH REAR FENDER	1	1,172.00	n	1,172.00 X
5 LH REAR FENDER	1	1,172.00	n	1,172.00 X
6 REAR BUMPER BEAM	1	300.00	As	300.00 ✓
7 REAR TOW COVER	1	16.00	n	16.00 X
8 REAR EXHAUST	1	601.80	R	601.80 X
Price and panel	As	450.00	✓	

20 Sub-Total: 5,074.20

Less: 25% discount - 1,014.84

Total Parts after 25% discount: 4,059.36

20

Parts : 1370.4 - 20%

=) 1096.32

Special Nett Items

1 Anti-rust coating

Acc review sent

S/N: 200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

80.00

320

n 160.00 X

Total SN: 160.00

Short 200.00 ✓

Total Parts: 4,219.36

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	2,000.00	600
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	2,000.00	660
3	Provide skill labour to disconnect and check electrical wiring	150.00	200
4	Remove and replacement of exhaust pipe to facilitate repair	250.00	78
5	Realign of exhaust	150.00	150

Total Labour:

Labour: 1280

Total Parts & Labour:

4,550.00

8,769.36

GST 7%

613.86

Grand Total:

9,383.22

Estimate Repair Duration

15 days

ACCIDENT VEHICLE OF : SLR8745U

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: NINJA LO

Survey attended by:

Name : Kenneth
Company : CLK
Date : 22/7/21
Time : 11.25am
Contact No :
Email :

Parts: 1370.40 - 20%

=> 1096.32

SN -> 200

Labour -> 1280

L/S (1280 + 1096.32) - 20%

=> 1879.456 + 200

=> \$2079.46