



1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Date of Accident : 16 July 2021

Mr Leow Hwee Tian @ Liao An Heng

Date : 21 July 2021

Estimate To Repair SKQ8504R - Toyota CAMRY 2.0 AUTO ABS AIRBAG

Chassis No : MR053BK4107016976

S/No	Quantity	Description	Amount
		LIST ITEMS	
01	1 pc	n/s front fender <i>good body</i>	\$ 810.00
02	1 pc	n/s front lower arm <i>nt</i>	\$ 235.90
03	1 pc	n/s front fender inner cowlings <i>D/S</i>	\$ 153.20
04	6 ps	n/s front fender inner cowlings clips @ \$4.50 <i>see</i>	\$ 27.00
05	1 pc	n/s headlamp <i>nt</i>	\$ 2,676.30
06	1 pc	n/s front door <i>nt</i>	\$ 1,280.00
07	1 pc	n/s front door protector <i>nt</i>	\$ 115.00
08	1 pc	n/s front absorber <i>nt</i>	\$ 435.80
09	1 pc	front bumper <i>de/to, n</i>	\$ 518.70
			\$ 6,251.90
		Less 25 %	\$ 1,562.98
			\$ 4,688.93
		SPECIAL NETT ITEMS	
10	1 pc	n/s front rim <i>Cut</i>	\$ 450.00
11	1 pc	n/s front tyre <i>See</i>	\$ 320.00
			\$ 770.00
		LABOUR & MISC. CHARGES	
01		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 650.00
02		Putty and spray painting of the affected portion.	\$ 750.00
03		To drop front n/s suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ <i>nt</i> 150.00
04		To check steering geometry and computer wheel alignment.	\$ 80.00
05		To check electrical lighting concerned.	\$ 60.00
06		To transfer of door fittings and perform water seepage test.	\$ <i>nt</i> 120.00
07		To rust-proofing of the affected areas.	\$ 150.00
08		To transfer of tyre, rim and on wheel balancing.	\$ <i>nt</i> 50.00
			\$ 2,010.00
			\$ 7,468.93
		LINK Auto Consultants hence notify the Repairer of the following:	
		• To resurvey & Total her spray painting	
		• To display damaged part(s) during resurvey	
		• Parts prices are subject to confirmation	
		• Third party survey is on a "Without Prejudice" basis	
		• No illegal modification(s) is allowed	
		• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
		<i>p- 1508.90 252 1/31-67 2541-67 2033.34</i>	
		Acknowledged by Damages	