

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 17/07/2021
TP Veh Reg No: SML3551P

Estimate No: EST2100193
Date: 19 Jul 2021

Veh Reg No: SLR7794J
Make/Model: MAZDA MAZDA 3
SEDAN 1.5 AT EU6
Chasis No: JM6BN22A8H0174300
Reg. Date: 28/08/2017
Your Ref No: SML3551P

Estimate Repair Cost to Vehicle No :SLR7794J

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
List Price			
1	1 PC REAR BUMPER <i>Dented</i>	1,128.60	✓
2	1 PC REAR BUMPER REINFORCEMENT <i>Dented</i>	564.20	✓
3	2 PCS REAR BUMPER SIDE RETAINERS <i>new</i>	96.00	+
4	1 PC REAR TOWING COVER <i>missing</i>	28.50	✓
		1,817.30	
	Less 20%	363.46	1,453.84
Special Net			
5	1 SET REVERSE SENSORS <i>and</i>	250.00 200	
6	1 SET REAR BUMPER CLIPS <i>re</i>	40.00 30	
		290.00	290.00
Labour			
7	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	600.00 200	
8	1 TO SPRAY PAINTING	600.00 200	
9	1 TO SPRAY UNDERSEAL	80.00	+
10	1 TO REPLACE REVERSE SENSORS	80.00 50	
11	1 TO CHECK WIRING	20.00	x
		1,380.00	1,380.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 17/07/2021
TP Veh Reg No: SML3551P

Estimate No: EST2100193
Date: 19 Jul 2021

Veh Reg No: SLR7794J
Make/Model: MAZDA MAZDA 3
SEDAN 1.5 AT EU6
Chasis No: JM6BN22A8H0174300
Reg. Date: 28/08/2017
Your Ref No: SML3551P

Estimate Repair Cost to Vehicle No :SLR7794J


Quantity	Description	List Price	Amount
		SS	SS
		Total	S\$ 3,123.84
		Add GST @ 7%	218.67
		Total Amount Payable	<u>S\$ 3,342.51</u>

TOTAL: SINGAPORE DOLLAR THREE THOUSAND THREE HUNDRED FORTY TWO AND CENTS FIFTY ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L.
2/s 27/07/21.
03 Days.
Total: 2057.04
2/s: 1650