

Date: 14/07/2021
Vehicle No: SNA967Y
Model: TOYOTA COROLLA HYBRID
Chassis: ZWE2116062247
Reg.Year: 2021

Third Party Insurer: AXA INSURANCE
Third Party Veh No: SJU3321A
Date of Accident: 19/07/2021
Estimator: Victor
Surveyor: Kenneth(LKK)

Not Insured
Recovery B&P paint
ESTIMATE

4-5 days

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	BOOTLID	1		<i>By</i> \$1,678.00
2	BOOTLID TOYOTA EMBLEM	1		<i>Re</i> \$110.00
3	BOOTLID COROLLA EMBLEM	1		<i>Re</i> \$95.00
4	BOOTLID HYBRID EMBLEM	1		<i>Re</i> \$100.00
5	BOOTLID LOCK	1		<i>R</i> \$458.20
6	REAR BUMPER	1		<i>By</i> \$2,530.00
7	REAR LOWER BUMPER	1		<i>Re</i> \$517.00
8	REAR SIDE RETAINER LH	1		<i>Re</i> \$145.00
9	REAR BUMPER REFLECTOR LH	1		<i>Re</i> \$127.00
10	END PANEL	1		\$1,188.00
11	END PANEL TOP COVER	1		<i>Re</i> \$245.00
SUB TOTAL				\$7,193.20
LESS 25%				-\$2,584.60
PARTS TOTAL				\$4,608.60

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>Re</i> \$100.00
2	END PANEL TOP COVER CLIPS	1		<i>Re</i> \$50.00
3	REVERSE SENSORS	1		<i>Re</i> \$240.00
S/N TOTAL				\$390.00

LABOUR CHARGES:

LABOUR CHARGES TO REPLACE, REPAIR, DISMANTLE AND REFIX ACCIDENT AREA. \$800.00 *7*

LABOUR CHARGES TO PAINT ON ACCIDENT AREA. \$1,000.00 *600*

TO CHECK AND RECTIFY ALL WIRING SYSTEM. \$60.00 *201*

TO REMOVE AND REFIT REVERSE SENSOR AND CONDUCT DISTANCE SETTING. \$100.00 *501*

CAVITY TREATMENT AND APPLY SEALANT. \$120.00 *?*

	LABOUR TOTAL	\$2,080.00
Vic	TOTAL	\$7,078.60

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

