

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
	Affiliated to Federation Internationale Des Experts En Automobile				
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21007872/Atf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	03/11/2021	
			Code:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJM 4865H	Veh. Inspected	SJY 2014Y	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10010985/KY	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	23/07/2021	
2. Vehicle Particulars & Condition					
	Make & Model	VOLKSWAGEN TOURAN	c.c	1390	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	WVGZZZ1TZAW114982	Colour	SILVER	
	Odometer	138995 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
	L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
	R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
	L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	19/07/2021	Inspection Date	23/07/2021	
	Survey held at	MG SOLUTION PTE LTD			
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a.	Remarks				
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.		Estimate Days of Repair			

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: