

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0027572
Sing Moh Electrical Engineering Pte
Ltd

Page 1 of 2
Your ref. TP-SLM 7658X INDIA
Job No. 72152
Our ref 21.07.13
Payment
Date 23/7/2021

Attn

Vehicle No SLV 6473X
Vehicle Model : Honda Vezel
Accident on ... 21/7/2021

Not Authorized

Recovery B4 paym

4-5 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear tailgate	1,037.00	20.00	829.60 ✓
1.00	Pc	Rear bumper	553.10	20.00	442.48 ✓
1.00	Pc	Rear bumper side RH	172.80	20.00	138.24 ✓
4.00	Pcs	Rear bumper clips	3.50	20.00	11.20 ✓
1.00	Pc	Rear Vezel emblem	38.80	20.00	31.04 ✓
2.00	Pcs	Rear windscreen moulding	31.00	20.00	49.60 ✓
1.00	Pc	Rear end panel	452.40	20.00	361.92 ✓
1.00	Pc	Rear end panel top cover	55.80	20.00	44.64 ✓
Special nett item:					
1.00	Set	Rear parking sensor with installation	200.00		200.00 ✓
Labour & Misc:					
1.00		To transfer rear camera	40.00		40.00 ✓
1.00		To remove + refix rear windscreen	140.00		140.00 ✓

LKK Auto Consultants hence notify the Reparer of the following:

- To return to the Reparer after spray painting
- To return to the Reparer during reassembly
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplier (14.5) must be re-inspected and is subject to their approval from Insurance Company

Acknowledged by Reparer: _____
Signature: _____
Date: _____

Sub-Total
GST 7.00%

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0027572
Sing Moh Electrical Engineering Pte Ltd

Page 2 of 2
Your ref. TP-SLM 7658X INDIA
Job No. 72152
Our ref. 21.07.13
Payment
Date 23/7/2021

Attn

Vehicle No SLV 6473X
Vehicle Model : Honda Vezel
Accident on ... 21/7/2021

22/07/2021 17:20 (SGT)
21/07/2021 22:30 (SGT)
Serangoon Ave 2, Singapore
Traffic light junction
Singapore

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To supply sealant	40.00		40.00 ✓
1.00		To straighten rear body, to knock dents on rear tyre panel and renew of parts	800.00		800.00 7
1.00		To spray paint	700.00		700.00 450/

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub-Total 3,828.72
GST 7.00% 268.01
Total S\$ 4,096.73

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。此外，还有先进的 SAICO Deluxe 喷漆烘炉。

Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support ally system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO deluxe oven heater for re-spraying all motor vehicles."