



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2106990

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 08/10/2021
Reference CC6/III21004512/Ags3q2-1
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SJN 393Z
Insured Veh. XE 1098B
Claim No. MFL2021D0001579
Policy No. D20MFL0004151
Accident Date 06/04/2021
Inspection Date 07/04/2021

Description	Total
Survey Inspection	600.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Merimen Fee	11.00
Note: Pls discard Inv.AC2104849 dated 09/07/2021 \$493.27	
Subtotal	611.00
GST (7%)	42.77
Grand Total	653.77

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM