

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007887/TEA3Q2**Date:** 20/06/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100504729
Claimant Vehicle No :	FBS5531C	Insured Vehicle No :	SLM2723Z
Date of Loss:	16/07/2021	Nature of Claim:	TP
		Claim No:	3449742304SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBS5531C	Engine No:	G3R1E0002325
Make & Model:	YAMAHA MTN155, 155cc	Chassis No:	MH3RG711000001134
Reg. Date:	28/05/2021 (Man. Year: 2020)	Odometer:	632 km
Colour:	Grey/White		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	140/70 R17
Front Left Side:	Winner 6 mm	Rear Left Side:	Winner 6 mm
Front Right Side:	Winner 0 mm	Rear Right Side:	Winner 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,169.25	1,015.95	153.30	13.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	927.00	640.00	287.00	30.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,096.25	1,655.95	440.30	21.00
+ GST 7.00/7.00% (S\$)	146.74	115.92	30.82	21.00
Nett Amount (S\$)	2,242.99	1,771.87	471.12	21.00
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,779.32		

INSPECTION

Date of Assignment:	23/07/2021	HONG LEONG CORPORATION HOLDINGS PTE LTD - Yamaha Division (HQ) 178 PAYA LEBAR ROAD #01-01 Singapore 409030
Date Inspected:	23/07/2021 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MUFFLER COMP 1	Dented	210.00 FL	*210.00 FL
2	1		*PROTECTOR MUFFLER	Cut	22.00 FL	*22.00 FL
3	1		*GUARD MUD	Cut	5.00 FL	*5.00 FL
4	1		*FRONT FORK ASSY	Bent	635.00 FL	*635.00 FL
5	1		*CALIPER ASSY (RHS)	Dented	70.00 FL	*70.00 FL
6	1		*HANDLEBAR	Cut	25.00 FL	*25.00 FL
7	2		*STOPPER	Necessary	6.00 FL	*6.00 FL
8	2		*END GRIP	Cut	12.00 FL	*12.00 FL
9	2		*BOLT HEX SOCKET HEAD	Necessary	5.00 FL	*5.00 FL
10	2		*WASHER PLATE	Necessary	3.00 FL	*3.00 FL
11	1		*PEDAL BRAKE	Dented	28.00 FL	*28.00 FL
12	1		*COVER ,SHIFT PEDAL	Necessary	1.50 FL	*1.50 FL
13	2		*PIN COTTER	Necessary	4.00 FL	*2.00 FL
14	1		*BRACKET 4	Cut	14.00 FL	*14.00 FL
15	1		*LEVER 1	Not Necessary	8.00 FL	*- FL
16	1		*SHIFT PEDAL ASSY	Not Necessary	20.00 FL	*- FL
17	1		*REAR VIEW MIRROR (LHS)	Not Necessary	7.00 FL	*- FL
18	1		*REAR VIEW MIRROR (RHS)	Cracked	7.00 FL	*7.00 FL
19	1		*CAP	Cut	30.00 FL	*30.00 FL
20	1		*BRAKE FLUID	Necessary	20.00 FS	*20.00 FS
21	1		*REAR NUMBER PLATE	Bent	28.00 FS	*28.00 FS
22	1		*RACK	Not Necessary	100.00 FS	*- FS
23	1		*FORK OIL	Not Necessary	20.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$)	1,280.50 1,123.50
					- List Item Discount on L Items 10.00/10.00% (\$)	111.25 107.55
					Total Parts (\$)	1,169.25 1,015.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING-2 WAY	New	80.00	80.00
2	LABOUR -ADJUST ALIGNMENT	New	120.00	80.00
3	LTA-VEHICLE INSURANCE ENQUIRY	New	7.00	0.00
4	LABOUR -REPLACE ACCIDENT PARTS	New	720.00	480.00
Gross Labour Cost (\$\$)			927.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >