



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL

INV No. AC2105276

50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWER
SINGAPORE 048623

INV Date 28/07/2021
Reference CS3/SMO21007899/Kqf3e2
Code SMO

PROFESSIONAL SERVICE FEE

Vehicle No. SLF 3137X
Insured Veh. SLL 8469Z
Claim No. CMTD2102204/MYE
Policy No. D21MTPV01006049
Accident Date 23/07/2021
Inspection Date 26/07/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 27.07.2021)	10.00
Subtotal	110.00
GST (7%)	7.70
Grand Total	117.70

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM