



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KITTY TEO			Ref: CC4/ASM21007925/Bpa3q2 Date: 20/04/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 7660M	Veh. Inspected	SJQ 4519L
	Policy No.	P2419140	Coverage (\$)	0.00
	Claim No.	S1M03DHT	Excess (\$)	0.00
	Assign From		Assign Date	26/07/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	MR053HY9305112445	Colour	WHITE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	POOR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	HANKOOK	6 mm
	L/H Front Tyre	195/55 R15	HANKOOK	6 mm
	R/H Rear Tyre	195/55 R15	HANKOOK	6 mm
	L/H Rear Tyre	195/55 R15	HANKOOK	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/07/2021	Inspection Date	26/07/2021
	Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	