

# PAIR ESTIMATE\*

VEHICLE NO SHC3122B

DATE 26.07.2021

MAKE :

MODEL : IONIQ G2

CHIANG/AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR RH FENDER			Ry \$1,768.30
1	REAR FENDER SHIELD RH			nn X \$173.60
1	WHEEL CAP RH			cut \$346.40
	<b>SUB TOTAL</b>		346.40	<b>\$2,288.30</b>
	<b>LESS 20%</b>			\$457.66
	<b>DISCOUNTED TOTAL</b>		277.12	<b>\$1,830.64</b>
1	REAR DOOR ADVERTISEMENT			cut \$100.00
1	REAR FENDER ADVERTISEMENT			cut \$100.00
1	REAR DOOR COMFORT APP			nn \$80.00
			280	<b>\$280.00</b>
	<b>Labour Charge</b>			
	Panel Beating		525	\$850.00
	Spray Painting Charge		500	\$600.00
	Tuff coat		nn X	\$90.00
	Remove/refix rear upholstery		nn X	\$90.00
	<b>TOTAL LABOUR</b>			<b>\$1,630.00</b>
	<b>ESTIMATE TOTAL</b>		91582.12	<b>\$3,740.64</b>
			03 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanp'm 17495749  
 'wp' 27/7/21 @ 4pm  
 p/p Resurvey new parts  
 2-3 days  
 tanp'm @ hkaup.com

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: