



TRANS EUROKARS PTE LTD



FINALIZE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L		NAME :		WIP :		38592			
3 ANSON ROAD		ADDRESS :		EXCESS :					
#16-00 SPRINGLEAF TOWER				DATE:		24-Jul-21			
SINGAPORE 079909		TEL :							
ATTN. : MOTOR CLAIMS									
FAX :									
VEH NO :	SMW174G	DATE IN :		CONTACT PERSON :		JESS			
CHASSIS NO :	JM6DJ2HAA01300532	MILEAGE :		TYPE OF CLAIM :		THIRD PARTY CLAIM			
MODEL :	MAZDA 2	DATE REG.	29-Oct-20	POLICY NO. :					
NATURE OF WORKS									
Parts Description									
NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	UNIT PRICE	DISC	REVISED	PRICES
1	REAR BUMPER	1	✓		MDC3R-50-221BBB	893.40	0%	893.40	893.40
2	BEACKET CENTER RR BUMPER	1			MKD53-50-251	5.40	0%		5.40
3	STAY RR BUMPER	2			MD09W-50-271A	11.40	0%		22.80
4	RETAINER LH	1	✓		MD09H-50-2J1A	27.20	0%	27.20	27.20
5	RETAINER RH	1	✓		MD09H-50-2H1	27.20	0%	27.20	27.20
6	FASTENER	7	✓		MB45A-56-146A	3.00	0%	21.00	21.00
7	SPLASH SHIELD RR RH	1			MD09H-50-340	62.30	0%		62.30
8	SPLASH SHIELD RR LH	1			MD09H-50-350	62.30	0%		62.30
9	GROMMET,SCREW	4	✓		MBHN1-50-0Z1A	2.70	0%	10.80	10.80
10	BODY,LIFT GATE	1	✓		MD0Y2-62-02X	956.70	0%	956.70	956.70
11	WTHSTP PARTING SEAL	1	✓		MD43N-62-76YA	58.10	0%	58.10	58.10
12	TRIM,LIFTGATE-LOWER	1	✓		MD09W-68-960	93.50	0%	93.50	93.50
13	FASTENER	9	✓		MGJ21-68-885B02	3.00	0%	27.00	27.00
14	RECESS,LIFT GATE	1			MD651-68-966B02	15.00	0%		15.00
15	CLIP,TRIM	2	✓		MGJ12-68-865	3.00	0%	6.00	6.00
16	COVER,HOLE TRUNK LID	2			MD24H-62-866	2.50	0%		5.00
17	VALVE,ONEWAY	2			MGHP9-58-867	12.00	0%		24.00
18	SWITCH,OPEN	1			MD09H-62-4B0C	89.70	0%		89.70
19	HINGE,LIFT GATE	2			MD09H-62-210	34.10	0%		68.20
20	MASCOT,REAR	1			MD09W-51-730	61.20	0%		61.20
21	ORNAMENT,MAZDA 2	1	✓		MDB2M-51-721	58.30	0%	58.30	58.30
22	ORNAMENT SKYACTIV	1	✓		MD09W-51-771	68.00	0%	68.00	68.00
23	CLIP,GARNISH	4	✓		MD09W-50-M38A	5.20	0%	20.80	20.80
24	SPOILER LHR SIDE	1			MD09W-51-9C0A	178.80	0%		178.80
25	WIPER MTR REAR	1			MD09L-67-450A	333.00	0%		333.00
26	SPACER	4			MGJ6A-50-897	12.80	0%		51.20
27	FASTENER	2			MC513-50-896	8.20	0%		16.40
28	FASTENER	2			MD204-50-896A	2.80	0%		5.60
29	LAMP,LICENSE	2			MD09H-51-270B	55.80	0%		111.60
						TOTAL PARTS		2,268.00	3,380.50
						TOTAL PARTS COS		2,268.00	3,380.50
SUPPLEMENTARY									

NO	DESCRIPTION	QTY	1st	Supp	PARTS NO			REVISED	PRICES
1									
2									
3									
					TOTAL PARTS				-
					TOTAL PARTS COST				-

Labour Description			REVISED	PRICES
1		REPLACE REAR BUMPER, TAILGATE. 167320	1,320.00	1,980.00
2		SPRAY REAR BUMPER, TAILGATE.	1,260.00	1,890.00
3	MZ-BR-GLASS	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	560.00	560.00
4	MZ-BR-GLASS	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	120.00	120.00
5	MZ-BR-REVERSE	TO TRANSFER REVERSE SENSORS.	150.00	660.00
10	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120.00	200.00
11	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180.00	250.00
13	MZ-BR-SUNDR	SUNDRIES.	20.00	50.00

<u>REMARKS:</u> THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR	TOTAL LABOUR	3,800.00	5,710.00
	TOTAL PARTS	2,268.00	3,380.50
	TOTAL	6,068.00	9,090.50
	LESS EXCESS	-	-
	TOTAL AFTER EXCESS	6,068.00	9,090.50
	GST 7%	424.76	636.34
	GRAND TOTAL	6,492.76	9,726.84

SUPPLEMENTARY LABOUR DESCRIPTION

			REVISED	PRICES
1	MZ-BR-PLATE	TO SUPPLY NUMBER PLATE.	70.00	70.00
2		#N/A	✓	

<u>REMARKS:</u> THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR	TOTAL LABOUR	70.00	70.00
	TOTAL PARTS	-	-
	TOTAL	70.00	70.00
	LESS EXCESS	-	-
	TOTAL AFTER EXCESS	70.00	
	GST 7%	4.90	-
	GRAND TOTAL	74.90	-

SURVEY BY : THEVAN OF LKK ON 28-7-2021
REPAIR DAYS : 4 DAYS

TRANS EUROKARS PTE LTD

9160.5

Authorised Signature

Finalize \$ 6068 / 5 repair days



Thevon Lhik