



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CHAN KIAN CHUAN			Ref: CS/ASM21007978/Ktce2 Date: 21/12/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 4187M	Veh. Inspected	FBL 432A	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M03EEQ	Excess (\$)	0.00	
Assign From	CHAN KIAN CHUAN	Assign Date	27/07/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SUZUKI GSX1300RAL6	c.c	1340	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JS1CK1116G0100291	Colour	METALLIC RED / GREY	
Odometer	28972 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	120/70Z R17	BRIDGESTONE	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	200/55Z R17	BRIDGESTONE	6 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/07/2021	Inspection Date	28/07/2021	
Survey held at	S THREE AUTOMOTIVE & RECOVERY PTE LTD BLK 8 SIN MING IND EST #01-64/66 SINGAPORE 575643			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	