

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 28 Jul 2021

Preliminary Advice

Vehicle No	: SLE9057J	Accident Date	: 19/07/2021
Make	: SUBARU IMPREZA	Policy No.	: DMPCSNW00063462100
Assignment Date	: 27/07/2021	Excess	: S\$250.00
Date of Inspection	: 27/07/2021	Est. Duration of Repair	: 0
Inspection At	: CAR CITY AUTO CENTRE PTE LTD (HQ) BLK 9006 #01-198, TAMPINES STREET 93 SINGAPORE 528840		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	79,000.00
COE / PARF Rebate	:S\$	44,247.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,753.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :