



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG			Ref: CC4/ASM21007982/Uba3q2 Date: 30/09/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 9531U	Veh. Inspected	GBB 7351G
	Policy No.	VFX/P2413997	Coverage (\$)	0.00
	Claim No.	S1M03EBM	Excess (\$)	0.00
	Assign From		Assign Date	27/07/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN URVAN (M)	c.c	2953
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	JN1MG4E25Z0792848	Colour	SILVER
	Odometer	351007 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm
	L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/07/2021	Inspection Date	27/07/2021
	Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	