

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile							
	CHINA TAIPING IN	F	Ref:	CS/CTI21007985/c			
	3 ANSON ROAD # SPRINGLEAF TO\	С	Date:	27/07/2021			
			C	Code:	CTI		
1.	. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJG 8417Z	Veh. Inspected		SLJ 2646D		
	Policy No.		Coverage (\$)		0.00		
	Claim No.	SNM21D204080/C02/SJG8417 Z/TANCHC	Excess (\$)		0.00		
	Assign From	JACQUELINE TAN	Assign Date		27/07/2021		
2. Vehicle Particulars & Condition							
	Make & Model		c.c		0		
	Engine No.	HIDDEN	Year of Reg.				
	Chassis No.		Colour				
	Odometer	-	Steering				
	Brakes		Modification				
	General						
3.	Conditions of Tyres						
		Size	Make		Balance		
	R/H Front Tyre				mm		
	L/H Front Tyre				mm		
	R/H Rear Tyre				mm		
	L/H Rear Tyre				mm		
4.	Description of Damages						
5.	General Information						
	Accident Date	21/07/2021	Inspection Date		27/07/2021	03/08/2021	
	Survey held at	CHENG HOE MOTOR SERVICE	HOE MOTOR SERVICE				
		BLK 1019, YISHUN INDUSTRIAL PARK A #01-374 SINGAPORE 768761					
5a.	5a. Remarks						
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							