

CONNECT 3
 566 Woodlands Road (Mandai Estate) Singapore 728697
 Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com
 R o c : 5 3 3 6 0 0 6 1 L
 G S T : 5 3 3 6 0 0 6 1 L

Steve (LKK)

MR M
3 Apr
PIP
My AL Ry

QT21/CB7802K/TPC

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way
#21-01
SGX Centre 2
Singapore 068807

QUOTATION

Dear Sir,

Cost of Repair to Vehicle CB7802K

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	RH rear fender panel X R	1	1408.00	1408.00
2.	Labour to remove RH side glass to assist repair X	1	150.00	150.00
3.	Sealant X 7n	2	40.00	80.00
4.	Labour to remove RH trims, seats, upholstery to assist repair	1	120 300.00	300.00
5.	Labour charges	1	600.00	600.00
6.	Spray painting	1	700.00	400 700.00
SUB-TOTAL				S\$3,238.00

- Price before 7% gst

PIP - \$920

Thank you.

Yours faithfully,



Winnie Chai

HP: 9850-9666



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: