

RE: [For DY CTP's Support, Pls] Procurement to seek LKK for Mechanical Inspection

Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>

Wed 30/6/2021 6:50 PM

To: Sherwin Beh (LKK Auto) <SherwinBeh@lkkauto.com>; Naz (LKKAuto) <Naz@lkkauto.com>

Cc: Beifeng NG (SPF) <NG_Beifeng@spf.gov.sg>; Adrian LIM (SPF) <Adrian_LIM@spf.gov.sg>; Mohamed Yazid MOHAMMED YUSOFF (SPF) <Mohamed_Yazid_Mohammed_Yusoff@spf.gov.sg>; Raziz TAHAR (SPF) <Raziz_TAHAR@spf.gov.sg>; Siew Ping TANG (SPF) <TANG_Siew_Ping@spf.gov.sg>; Jocelyn LOH (SPF) <Jocelyn_Loh@spf.gov.sg>; Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **22 vehicles** below. Those in **red** are deemed to be **urgent**:

- a. **Case IAFP-IB-20210629 - Mechanical Inspection of Motorcycle, JQR8144 (TP/IP/26771/2021)**
- b. **Case IAFP-IB-20210629 - Mechanical Inspection of Van, GP6563K (TP/IP/26771/2021)**

On 1 June 2021, at about 10.24 a.m., B1 (GP6563K) was travelling along Keppel Road towards MCE after AYE, on lane 3 of a 3 lane road. At the same time, A1 (JQR8144) was travelling slightly ahead of B1 on lane 2 of a 3 lane road, on B1's right. While B1 was negotiating a right bend, Suddenly B1 skidded to her right. Hence, collided onto A1 who was on her right. The impact pushes both vehicle to the right and landed on the right of the road on the drainage. Due to the accident, A1 was conveyed to SGH by the SCDF ambulance in an conscious state. However, B1 claimed that there were possible mechanical fault. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: **JQR8144** - Rider (Victim)
 GP6563K - Driver (Potential Defendant)

IO In-Charge: SIO Ng Beifeng

- c. **Case IAFP-IB-20210629 - Mechanical Inspection of Motorcar, SLK2774L (TP/IP/28149/2021)**
- d. **Case IAFP-IB-20210629 - Mechanical Inspection of Motorcycle, FBQ6529P (TP/IP/28149/2021)**

On 9 June 2021 sometime before 8.43 a.m., the Involved Party was driving her motorcar along PIE (Changi Airport) near to 19.9km mark when the Deceased who was riding his motorcycle, FBQ6529P on lane 2, in the process of overtaking the involved party motorcar from the left, side swiped onto the left front portion of the Involved party motorcar, lost control to the right and collided onto the guard railing and landed on the center divider. Deceased was pronounced dead on the spot at 9.25am by attending paramedics. Pillion rider of motorcycle was conveyed to TTSH where she succumbed to her injuries and passed away on the same day at 9.33am at TTSH. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: **SLK2774L** - Driver (Involved Party)
 FBQ6529P - Rider and Pillion (Deceased Persons)

IO In-Charge: SIO Adrian Lim

- e. **Case IAFP-IB-20210629 - Mechanical Inspection of Motorcycle, FU6482X (TP/IP/27721/2021)**
- f. **Case IAFP-IB-20210629 - Mechanical Inspection of Van, GBG1047Z (TP/IP/27721/2021)**
- g. **Case IAFP-IB-20210629 - Mechanical Inspection of Tipper, XE464J (TP/IP/27721/2021)**

On 7 June 2021 at about 0821 hrs, the rider of motorcycle, FU6482X was travelling along Woodlands Avenue 12 towards SLE on lane 1 of 3 lanes when the motorcycle collided onto rear of a van, GBG1047Z which was stationary due to red light ahead. On impact, the rider and his pillion fell into lane 2 where both rider and pillion were believed to be ran over by the rear right tyres of tipper, XE464JJ, that was travelling on lane 2 of 3-lane road. The pillion was pronounced dead at the scene while the rider was sent to KTPH for serious injuries. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: FU6482X - Rider (Seriously Injured) and Pillion (Deceased)
GBG1047Z - Driver (Involved Party)
XE464J - Driver (Involved Party)

IO In-Charge: DOC Yazid

- h. **Case IAFP-IB-20210629 - Mechanical Inspection of Bus, PC3857U (TP/IP/22175/2021)**
i. **Case IAFP-IB-20210629 - Mechanical Inspection of Bicycle (TP/IP/22175/2021)**

On 3 May 2021 at about 8.43 p.m., the deceased was cycling on the pavement of Nanyang Drive when she fell off her bicycle and fell onto the road into the path of an incoming bus, PC3857U, that was travelling on the single lane road. The said bus subsequently ran over the deceased and due to the impact, the Deceased was pronounced dead at the scene by the attending paramedic. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: PC3857U - Driver (Involved Party)
Bicycle - Pedal Cyclist (Deceased)

IO In-Charge: DOC Yazid

- j. **Case IAFP-IB-20210629 - Mechanical Inspection of Motorcycle, FBD9918Z (TP/IP/27321/2021)**
k. **Case IAFP-IB-20210629 - Mechanical Inspection of Van, GBH2727H (TP/IP/27321/2021)**

On 3 June 2021 at about 2301 hrs, the rider of motorcycle, FBD9918Z, was making a right turn along Airport Road into Bartley Road East when lorry, GBH2727H, that was travelling straight on the opposite direction collided onto the motorcycle. The Deceased was sent to TTSH pulseless and was pronounced dead on the same day at TTSH. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: FBD9918Z - Rider (Deceased)
GBH2727H - Driver (Involved Party)

IO In-Charge: DOC Yazid

- l. **Case IAFP-IB-20210629 - Mechanical Inspection of Truck, XE7733L (TP/IP/19813/2021)**
m. **Case IAFP-IB-20210629 - Mechanical Inspection of Lorry, YP6143B (TP/IP/19813/2021)**

On 20 April 2021 (Tuesday) at 6.06 a.m., the Involved Party (who was driving motor truck XE7733L) was stationary along the road shoulder of PIE (AP) 36.9km, when the Defendant (who was driving motor lorry YP6143B) collided onto the rear of the Involved Party's motor truck. As a result of the accident, the two passengers of the motor lorry sustained head injuries and were pronounced dead at the hospital. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: XE7733L - Driver (Involved Party)
YP6143B - Driver (Deceased)

IO In-Charge: SIO Raziz

- n. **Case IAFP-IB-20210629 - Mechanical Inspection of Motorcar, SLM6734R (TP/IP/18961/2021)**

On 15 April 2021 (Thursday) at 2.37 p.m., the Involved Party (who was driving motorcar SLM6734R) was travelling along service road of Toa Payoh Lorong 6 when he collided onto the Deceased, who was crossing across the road from the Involved Party's left to right. As a result of the accident, the Deceased sustained head injuries and was pronounced dead at the hospital. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: SLM6734R - Driver (Potential Defendant)

IO In-Charge: SIO Raziz

- o. **Case IAFP-IB-20210629 - Mechanical Inspection of Truck, XD2517H (TP/IP/23985/2021)**
p. **Case IAFP-IB-20210629 - Mechanical Inspection of Motorcycle, FBN9371Y (TP/IP/23985/2021)**

On 15 May 2021 (Saturday) at 10.50 a.m., the Involved Party (who was driving motor trailer XD2517H) driving his trailer along Tuas South Avenue 5 towards End on lane 1 of 3-lane road. While travelling straight along the said road, the Deceased who was riding the motorcycle FBN9371Y, on the opposite direction suddenly veered to the right, cut across the centre chevron markings and collided onto the right portion of the Involved Party's trailer. The Deceased's motorcycle subsequently skidded and landed on lane 1 of 3-lane road along Tuas South Avenue 5 towards Tuas Avenue 18. As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: XD2517H - Driver (Involved Party)
FBN9371Y - Rider (Deceased)

IO In-Charge: SIO Raziz

- q. **Case IAFP-IB-20210629 - Mechanical Inspection of Motorcycle, FBA994C (TP/IP/24779/2021)**

On 19 May 2021 (Wednesday) at 9.33 a.m., the Deceased (who was riding motorcycle, FBA994C alone) was travelling along Woodlands Road slip road into KJE (PIE), which was left bend when he lost control of his motorcycle and self-skidded. As a result of the accident, the Deceased sustained chest injuries and was pronounced dead at the hospital. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: FBA994C - Rider (Deceased)

IO In-Charge: SIO Raziz

- r. **Case IAFP-IB-20210629 - Mechanical Inspection of Trailer, JRF6322 (TP/IP/26557/2021)**
s. **Case IAFP-IB-20210629 - Mechanical Inspection of Bicycle (TP/IP/26557/2021)**

On 31 May 2021 (Saturday) at 4.25 p.m., the Involved Party (who was driving motor trailer JRF6322) driving his trailer along Marina East Drive towards End on lane 2 of 3-lane road. While travelling straight along the said road, the Deceased who was cycling against the flow of traffic along lane 3 of 3-lane road suddenly veered to the left and encroached into lane 2 of 3-lane road thus resulting in a collision with the left rear portion of the Involved Party's motor trailer. As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: JRF6322 - Driver (Involved Party)
Bicycle - Pedal Cyclist (Deceased)

IO In-Charge: SIO Raziz

- t. **Case IAFP-IB-20210629 - Mechanical Inspection of Police Truck, YQ2025E (TP/IP/24847/2021)**

On 19 May 2021 at about 3.36p.m., the Involved Party (who was driving Police truck YQ2025E) was travelling Nicoll Highway towards Esplanade Drive on lane 3 of 3-lane road when the vehicle suddenly veered to the right thus resulting in a sideswipe collision with a tipper truck which was travelling on lane 2 of 3-lane road. The driver of Police truck, YQ2025E, claimed there was mechanical fault to the steering wheel which caused the vehicle to veer to the right. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: YQ2025E - Driver (Potential Defendant)

IO In-Charge: SIO Raziz

u. **Case IAFP-IB-20210629 - Mechanical Inspection of Motorcar, SJZ7223Y (TP/IP/29221/2021)**

On 18 June 2021 at about 0246hrs along Seletar Club Road, the driver of motorcar, SJZ7223Y, reversed and hit into a motorcar. Subsequently, he reversed again and hit onto a Police car and his vehicle rolled back and hit onto the Police car again. The driver is unsure if there is any mechanical fault. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: SJZ7223Y - Driver (Potential Defendant)

IO In-Charge: SIO Siew Ping

v. **Case IAFP-IB-20210629 - Mechanical Inspection of MoBike Bicycle (TP/IP/29173/2021)**

On 16 June 2021 at about 3 p.m., the Deceased was cycling along the downslope of Clifton Vale and lost control of the bicycle, resulting in a collision with a concrete wall. Due to the accident, the Deceased who was reported to be unconscious and sustained head injury, was conveyed to Tan Tock Seng Hospital. On 17 June 2021 at 2.38 a.m., the Deceased succumbed to his injuries and was pronounced dead in Tan Tock Seng Hospital by Dr Oo Shuwen. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: MoBike Bicycle - Rider (Deceased)

IO In-Charge: SIO Kamaliah

2. These request has been approved by my management.

3. Thank you, Sirs.

cc: SIO Beifeng, SIO Adrian, DOC Yazid, SIO Raziz & SIO Siew Ping, as requested by you
Mr Bryan & OC FAIT, fyip

Best regards,

Kamaliah Kamis (Miss)

Senior Investigation Officer | Fatal Accident Investigation Team

Traffic Police Department | Singapore Police Force

DID: (65) 6547 6435 | FAX: (65) 6547 6352



Singapore Police Force [W police.gov.sg](http://www.police.gov.sg) [FB fb.com/singaporepoliceforce](https://www.facebook.com/singaporepoliceforce) [IG Instagram.com/singaporepoliceforce](https://www.instagram.com/singaporepoliceforce)

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."