



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref: CS3/AIG21008022/Bqf3	
78 SHENTON WAY #09-16		Date: 28/07/2021	
AIG BUILDING			
SINGAPORE 079120		Code: AIG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBJ 8155H	Veh. Inspected	CB 6997M
Policy No.		Coverage (\$)	0.00
Claim No.	7601624388SG	Excess (\$)	0.00
Assign From	DIVYASHNI SUBRAMANIAM	Assign Date	28/07/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	27/07/2021	Inspection Date	18/08/2021
Survey held at	ANN JOO MOTOR PL BLK 176 SIN MING DRIVE #02-17 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			