

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ECICS LTD		Ref: CS/ICS21008035/Atf3	
10 EUNOS ROAD 8		Date: 29/07/2021	
SINGAPORE POST CENTRE #09-04A			
SINGAPORE 408600		Code: ICS	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLZ 7033E	Veh. Inspected	SJW 3554J
Policy No.		Coverage (\$)	0.00
Claim No.	DMPC2100244H/02/CT	Excess (\$)	0.00
Assign From	CRYSTABELLE TAN GEK PENG	Assign Date	29/07/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	27/07/2021	Inspection Date	02/08/2021
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			