

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

GST: 53360061L

QT21/PD1131M/TPC

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way
#21-01
SGX Centre 2
Singapore 068807


Dear Sir,

Cost of Repair to Vehicle PD1131M


With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)	
1.	Front LH rear view mirror assy / CUT	1	1,750.00	1,750.00	-10% 1575
2.	Check wiring	1	20.00	20.00	✓
10.	Labour charges	1	300.00	300.00	200
11.	Spray painting	1	250.00	150 250.00	
SUB-TOTAL				S\$2,320.00	

- Price before 7% gst

Thank you.
Yours faithfully,
Winnie Chai

HP: 9850-9666



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Stew (LKK)
30/7/21, H. 21CML R 1945
2 4/1
P/P
M ML H