



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2107289

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 20/10/2021
Reference CC4/GRB21008065/Ubs3q2
Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. SKX 1891G
Insured Veh. SLM 7833G
Claim No. MFL2021D0003213
Policy No. D21MFL0000447
Accident Date 23/07/2021
Inspection Date 10/08/2021

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Merimen Fee	11.00
Mutual Settlement	150.00
Subtotal	511.00
GST (7%)	35.77
Grand Total	546.77

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM