

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697
Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT21/CB8025E/TPC

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

QUOTATION

Dear Sir,

Cost of Repair to Vehicle CB8025E

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front bumper / BR	1	637.50	637.50 ✓
2.	Front bumper clips / APC	10	3.00	30.00 ✓
3.	Front bumper LH retainer / BR	1	233.75	120 / 233.75
4.	Front LH headlamp / CUT	1	1,168.75	1,168.75 ✓
5.	Front LH passenger door / DD	1	2,252.50	1611 / 2,252.50
6.	Front LH passenger door hinge ? X nn 2	2	385.00	770.00 X
7.	Front LH step garnish / BR	1	191.25	191.25 ✓
8.	Front LH rear view mirror (big) / BR	1	1,147.50	1,147.50 ✓
9.	Front LH small blind spot mirror / BR	1	289.00	212 / 289.00
10.	Front LH small blind spot mirror cover / CUT	1	106.25	87 / 106.25
11.	Front LH door visor / BR	1	65.00	50 / 65.00
12.	Rear LH side panel / DD	1	3,781.30	1889 / 3,781.30
13.	LH sliding door / DD	1	2,894.55	1827 / 2,894.55
14.	LH sliding door roller assy lower X nn	1	515.49	515.49 X
15.	LH sliding door roller assy uuper X nn	1	130.00	130.00 X


16.	LH sliding door control assy (lock remote) X nn l	1	759.00	759.00	X
17.	LH sliding door motor assy X nn	1	1,954.42	1,954.42	X
18.	LH sliding door support side step X nn	1	625.87	625.87	X
19.	LH sliding door sensor assy (power slide door) X nn 1	1	1,155.20	1,155.20	X
20.	LH sliding door stopper X nn	1	45.00	45.00	X
21.	LH sliding door upper hinge assy X nn	1	246.00	246.00	X
22.	LH sliding door handle sub assy (inside) X nn 1	1	171.40	171.40	X
23.	LH sliding door handle assy (outside) X nn 1	1	236.70	236.70	X
24.	LH sliding door lock assy X nn	1	320.00	320.00	X
25.	LH sliding door glass X nn	1	548.00	548.00	X
26.	LH sliding door lock assy (front) X nn	1	297.50	297.50	X
27.	LH sliding door lock assy (full open & stop) X 1 nn	1	425.00	425.00	X
28.	LH sliding door trim X nn	1	310.70	310.70	X
29.	LH sliding door weatherstrip X nn	1	267.90	267.90	X
30.	LH fuel cover panel (Door rear pillar) / MC 1	1	1,615.00	1488 / 1,615.00	
31.	Rear bumper X nn	1	576.40	576.40	X
32.	Rear bumper clips X nn	10	3.00	30.00	X
33.	Rear LH corner panel X nn	1	147.00	147.00	X
34.	Sealant / MC	4	40.00	160.00	/
35.	LH taillamp / BR	1	2,550.00	354 / 2,550.00	
36.	Bolt Nuts & clips / MC	1	11,013 60.00	30 / 60.00	
37.	Private hire sticker (Schm) Bus) / MC	1	8259-75 15.00	15.00	/
38.	Labour to remove LH side glasses to assist repair	1	300.00	280 300.00	
39.	Labour to remove LH seats, trims, upholstery etc to assist repair	1	200.00	170 200.00	
40.	Transfer LH sliding door fittings	1	150.00	120 150.00	
41.	Transfer LH passenger door fittings	1	150.00	100 150.00	

42.	Check wiring	1	50	80.00	80.00
43.	Apply anti rust	1	60	80.00	80.00
44.	Labour charges	1	1700	1,800.00	1,800.00
45.	Spray painting	1	2100	2,200.00	2,200.00
SUB-TOTAL					S\$31,688.93

- Price exclude 7%gst

Yours faithfully,

Winnie Chai
HP: 9850-9666



P-8259.75

L- 4580

12,839-75

L/S- 10,271.80
= 10,250.00

Steve (LKK)

30/7/21, 11-30am

WIL AL

L/S

M AL SY

14 dys

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: