LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd. 8 Temasek Boulevard #04-01 Suntec Tower Three

Singapore 038988

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 04 Aug 2021

Preliminary Advice

Insured Vehicle No : GBG7629E

TP Vehicle No : SHB7724T Accident Date : 29/07/2021

Make : TOYOTA PRIUS Assignment Date : 30/07/2021

Date of Inspection : 02/08/2021 Est. Duration of Repair : 5

Inspection At : TRANS-CAB AUTO SERVICES PTE LTD

NO 2 ANG MO KIO STREET 63

SINGAPORE 569111

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,761.50
Revised Amount	:S\$	5,995.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,995.10

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

Remarks

(

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: WP SURVEHY