

(08/11/13) wef

ASS. REC. BY: *Paul*

REF:

2006

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLM 901SM*

at Workshop m/s

Borneo Motor

of

2, PANDAN CRESCENT

Insured:

LPC

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

71K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLM 901SM

Yr Regn:

*2011 / APR*Type: *M. Car* / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA PRIUS HYBRID 1.8 CVT c.c 1798

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

455714

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

3TDKB3FU 503555264

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / *DUN* / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

29/07/21

Survey held at

BORNEO Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Int - 36K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Incharge
 Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1	Bodysshop Retail Cash Sales Pandan TCBC Toyota Bodysshop Retail Cash Sales Pandan TCBC Toyota				
		Document No. 0					
		Document Date 29/07/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	17/04/2017	SLM9015M	0	63657	73/DS/SLM9015M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDK3FU503555264	2ZRS034797	60	Ary Chua	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE:28/07/2021 ACC DATE:28/07/2021@12.05PM TP VEH:XE2148J DRIVE IN:28/07/2021 TP Insurer: LONPAC Ins. DATE SURVEY:Rasul(LKKAUTO)29/07/2021@14.14pm NO OF REPAIR DAYS: 14 DAYS				30.00	
2	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR RH DOOR				60.00	
3	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.				122.40	
4	B	BP-LAB2 TO TRANSFER RHR DOOR GLASS,BOARD ,MECHANISM TO NEW PANEL.				360.00	
5	B	BP-LAB2 TO REPLACE REAR RH SIDE ACCIDENT DAMAGE PARTS.STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS. @720 x 5				3600 4320.00	
6	B	BP-RES2 TO SPRAY PAINT ON REAR RH SIDE ACCIDENT AFFECTED AREAS. @520 x 4				2360 3540.00	
7	1	U81551-47283 LENS & BODY, RR	1.00	456.50		456.50	
8	2	U81581-47011 LENS & BODY, RR	1.00	506.70		506.70	
9	3	U52159-47913 COVER, RR BUMPER	1.00	447.20		447.20	
10	4	U52453-47010 GUARD, RR BUMPER,	1.00	582.20		582.20	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle 	Parts		Less		
			Labour				
			Sublet				
			Lubrication/Fluid				
		Others		Amount Due			

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLP11	Bodyshop Retail Cash Sales Pandan TCBC Toyota Bodyshop Retail Cash Sales Pandan TCBC Toyota	
		Document No.		
		0		
		Document Date		
		29/07/2021		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	17/04/2017	SLM9015M	0	63657	73/DS/SLM9015M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU503555264	2ZRS034797	60	Ary Chua	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	5	U52161-16010				
12	6	U52565-47900				
13	7	U52575-47040				
14	8	U52576-47040				
15	9	U52023-47030				
16	0	U61601-47150				
17	1	U61621-47050				
18	2	T08826-08115				
19	3	U62940-47010				
20	4	U62505-47011				
21	5	U75763-47010				
22	6	U75730-47040				
23	7	U75765-47010				
24	8	U67003-47211				
25	9	U75977-47080				
26	0	U75987-47060				
27	1	U75979-47070				
28	2	U69050-52250				
29	3	U69803-47020				
30	4	U85720-47150				
		PIECE, RR BUMPER	10.00	4.50		45.00
		FILLER, RR BUMPER	1.00	124.90		124.90
		RETAINER, RR BUMPER	1.00	118.90		118.90
		RETAINER, RR BUMPER	1.00	117.70		117.70
		REINFORCEMENT	1.00	336.30		336.30
		PANEL SUB-ASSY,	1.00	881.80		881.80
		TROUGH, BACK DOOR	1.00	104.60		104.60
		PANEL BONDING AD	1.00	267.20		267.20
		DUCT ASSY, QUARTER	1.00	67.50		67.50
		COVER SUB-ASSY,	1.00	209.10		209.10
		MOULDING, RR DOOR	1.00	93.20		93.20
		MOULDING ASSY, RR	1.00	114.70		114.70
		MOULDING, RR DOOR	1.00	39.00		39.00
		PANEL SUB-ASSY, RR	1.00	1306.50		1306.50
		STRIPE, RR DOOR	1.00	22.10		22.10
		STRIPE, RR DOOR	1.00	35.30		35.30
		STRIPE, RR DOOR	1.00	15.50		15.50
		LOCK ASSY, RR DOOR	1.00	567.30		567.30
		REGULATOR SUB-ASSY	1.00	208.40		208.40
		MOTOR ASSY, POWER	1.00	932.80		932.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	
			Less
			Amount Due



Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLP11		Bodyshop Retail Cash Sales Pandan TCBC Toyota Bodyshop Retail Cash Sales Pandan TCBC Toyota			
			Document No. 0					
			Document Date 29/07/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q3	17/04/2017	SLM9015M	0	63657	73/DS/SLM9015M	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU503555264		2ZRS034797	60	Ary Chua	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
31	5	L90269-04051 RIVET <i>na</i>			1.00	1.50		1.50
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____ <i>Rasul</i> <i>Hp 90010068</i> <i>9 days</i> <i>29/07/21 @ 1430</i> <i>Reg before paint</i> <i>rasul@lkkauto.com</i>								
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle				16,034.30		
				Parts 7,601.90		GST 7.00% 1,122.40		
				Labour 8,432.40		Less 0.00		
				Sublet 0.00				
				Lubrication/Fluid 0.00				
				Others 0.00		Amount Due 17,156.70		

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	200G
Vehicle No.:	SLM9015M
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jul 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZR5034797
Chassis No.:	JTDKB3FU503555264
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	17 Apr 2017
First Registration Date:	17 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Information for PARF Eligibility	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Apr 2027
PARF Rebate Amount:	\$3,750.00
Information for COE Rebate	
COE Expiry Date:	16 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,000.00
COE Rebate Amount:	\$30,854.00
Total Rebate Amount:	\$34,604.00

The information contained herein is correct as at 30 Jul 2021

OK

Toyota Prius Hybrid 1.8A

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price	\$73,800		
Depreciation ?	\$12,180 /yr View models with similar depre	Reg Date .	07-Jun-2017 (5yrs 10mths 7days COE left)
Mileage	43,000 km (10.4k /yr)	Manufactured ?	2017
Road Tax ?	\$976 /yr	Transmission	Auto
Dereg Value ?	\$34,842 as of today (change)	Fuel Type	Petrol-Electric
COE ?	\$53,106	OMV ?	\$29,007
Engine Cap	1,798 cc	ARF ?	\$5,000
Curb Weight ?	1,375 kg	Power	90.0 kW (120 bhp)



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLP11	M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925
	Document No. 0	
	Document Date 05/08/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	17/04/2017	SLM9015M	0	63658	73/oD/SLM9015M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU503555264	2ZRS034797	60	Ary Chua	03/08/2021 8.00	05/08/2021 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
17	3	U75754-47010 MOULDING, FR DOOR <i>na</i>	1.00	93.20		93.20
18	4	U75764-47010 MOULDING, RR DOOR <i>na</i>	1.00	93.20		93.20
19	5	L90269-04051 RIVET <i>na</i>	10.00	1.50		15.00
20	6	U75979-47070 STRIPE, RR DOOR, <i>na</i>	1.00	15.50		15.50
21	7	U75987-47060 STRIPE, RR DOOR, <i>na</i>	1.00	35.30		35.30
22	8	U75977-47080 STRIPE, RR DOOR, <i>na</i>	1.00	22.10		22.10

2 days
29/07/21 @ 1430
Reg 50 fine paint

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total 11,754.60
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others 5,397.10 6,357.50 0.00 0.00 0.00	GST 7.00% Less 822.82 0.00
			Amount Due 12,577.42



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLPI1		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 05/08/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	17/04/2017	SLM9015M	0	63658	73/oD/SLM9015M
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU503555264		2ZRS034797	60	Ary Chua	03/08/2021 8.00		05/08/2021 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	B	BP-DR RENEW DOOR GLASS				242/	332.50
2	B	BP-LAB2 TO TRANSFER BOTH FRONT AND REAR DOOR GLASS, BOARD, MECHANISM AND OTHER ATTACHMENT TO NEW PANELS.				720/	1440.00
3	B	BP-LAB2 TO REPLACE LH SIDE ACCIDENT DAMAGE PARTS @ 720 X 2				1440/	2520.00
4	B	BP-RES2 TO SPRAY PAINT ON LH SIDE ACCIDENT AFFECTED AREAS. (3p) @ 540 X 2.5				1475/	2065.00
5	1	U67002-47163 PANEL SUB-ASSY, FR <i>bt</i>	1.00	1312.30			1312.30
6	2	U75976-47060 STRIPE, FR DOOR, <i>ne</i>	1.00	13.40			13.40
7	3	U75986-47050 STRIPE, FR DOOR, <i>ne</i>	1.00	44.00			44.00
8	4	U75966-47030 STRIPE, FR DOOR, <i>ne</i>	1.00	26.60			26.60
9	5	U68102-47230 GLASS SUB-ASSY, FR <i>ca</i>	1.00	824.10			824.10
10	6	U69210-47051 A1 HANDLE ASSY, FR <i>ca</i>	1.00	394.80			394.80
1	7	U69202-47040 FRAME SUB-ASSY, FR <i>ne</i>	1.00	195.40			195.40
2	8	U67004-47211 PANEL SUB-ASSY, RR <i>bt</i>	1.00	1306.50			1306.50
3	9	U75978-47080 STRIPE, RR DOOR, <i>ne</i>	1.00	22.10			22.10
4	0	U75988-47060 STRIPE, RR DOOR, <i>ne</i>	1.00	35.30			35.30
5	1	U75989-47070 STRIPE, RR DOOR, <i>ne</i>	1.00	15.50			15.50
6	2	U85710-47150 MOTOR ASSY, POWER <i>short - photo?</i>	1.00	932.80			932.80
r & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy